

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin

LD0001G	Overall LMA Rating	Total LMA Miles				
Levee District No. 0001 (Glenn County)	U	12.45				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	2.80		2.80	22.49%		
Trim / Thin Trees	0.11		0.11	0.88%		
Encroachments	0.33		0.33	2.65%	0.07	
Animal Control	0.86		0.86	6.91%		
Slope Stability	0.01		0.01	0.08%		
LMA Totals:	4.11	0.00	4.11	33.01%	0.07	0.00

LD0001S	Overall LMA Rating	Total LMA Miles	* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.			
Levee District No. 0001 (Sutter County)	M *	16.65				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Encroachments	0.01		0.01	0.06%	0.62	
Supplemental						
USACE Erosion Survey		0.22	0.88	5.29%		
LMA Totals:	0.01	0.22	0.89	5.35% *	0.62	0.00

LD0002	Overall LMA Rating	Total LMA Miles				
Levee District No. 0002 (Glenn County)	A	4.89				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	0.14		0.14	2.86%		
Encroachments					0.01	
Animal Control	0.14		0.14	2.86%		
LMA Totals:	0.28	0.00	0.28	5.73%	0.01	0.00

LD0003	Overall LMA Rating	Total LMA Miles				
Levee District No. 0003 (Glenn County)	U	12.24				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Trim / Thin Trees	0.17		0.17	1.39%		
Encroachments	0.16		0.16	1.31%		
Animal Control	1.79		1.79	14.62%		
Slope Stability	0.04		0.04	0.33%		
Erosion / Bank Caving	0.01		0.01	0.08%		
Supplemental						
USACE Erosion Survey		0.20	0.80	6.54%		
LMA Totals:	2.17	0.20	2.97	24.26%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

LD0009	Overall LMA Rating	Total LMA Miles				
Levee District No. 0009 (Sutter County)	A	6.24				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Encroachments	0.02		0.02	0.32%	0.34	0.01
Animal Control	0.02		0.02	0.32%		
Erosion / Bank Caving	0.07		0.07	1.12%		
LMA Totals:	0.11	0.00	0.11	1.76%	0.34	0.01

MA0001	Overall LMA Rating	Total LMA Miles				
Not Inspected; 2009 Data	A	17.12				
Sutter Maintenance Yard Maintenance Area 0001						
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Vegetation	0.02		0.02	0.12%		
Trim / Thin Trees	0.03		0.03	0.18%		
Encroachments	0.02		0.02	0.12%	0.05	0.41
Animal Control	1.61		1.61	9.40%		
Erosion / Bank Caving	0.01		0.01	0.06%		
LMA Totals:	1.69	0.00	1.69	9.87%	0.05	0.41

MA0003	Overall LMA Rating	Total LMA Miles				
Sutter Maintenance Yard Maintenance Area 0003	A	5.19				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Animal Control	0.02		0.02	0.39%		
LMA Totals:	0.02	0.00	0.02	0.39%	0.00	0.00

MA0004	Overall LMA Rating	Total LMA Miles				
Sacramento Maintenance Yard Maintenance Area 0004	A	3.40				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Trim / Thin Trees	0.16		0.16	4.71%		
Encroachments					2.17	
Erosion / Bank Caving	0.01		0.01	0.29%		
LMA Totals:	0.17	0.00	0.17	5.00%	2.17	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

MA0005		Overall LMA Rating	Total LMA Miles	* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.			
Sutter Maintenance Yard Maintenance Area 0005		M *	33.32				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee							
Vegetation		0.02		0.02	0.06%		
Encroachments		0.10		0.10	0.30%		0.01
Animal Control		0.03		0.03	0.09%		
Slope Stability		0.01		0.01	0.03%		
Repair Gates		0.01		0.01	0.03%		
Supplemental							
USACE Erosion Survey			0.03	0.12	0.36%		
LMA Totals:		0.17	0.03	0.29	0.87% *	0.00	0.01

Unit No. 01 Butte Creek 1		Overall Unit Rating	Total Unit Miles	* Overall Unit Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall Unit Rating is M instead of A.			
MA0005		M *	15.29				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee							
Vegetation		0.01		0.01	0.07%		
Encroachments		0.04		0.04	0.26%		
Repair Gates		0.01		0.01	0.07%		
Supplemental							
USACE Erosion Survey			0.03	0.12	0.78%		
Unit Totals:		0.06	0.03	0.18	1.18% *	0.00	0.00

Unit No. 02 Butte Creek 1		Overall Unit Rating	Total Unit Miles				
MA0005		A	16.53				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee							
Vegetation		0.01		0.01	0.06%		
Encroachments		0.06		0.06	0.36%		0.01
Animal Control		0.03		0.03	0.18%		
Slope Stability		0.01		0.01	0.06%		
Unit Totals:		0.11	0.00	0.11	0.67%	0.00	0.01

Unit No. 03 Little Chico Creek Diversion 1		Overall Unit Rating	Total Unit Miles				
MA0005		A	1.50				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
No Items							
Unit Totals:		0.00	0.00	0.00	0.00%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

MA0007		Overall LMA Rating	Total LMA Miles			
Sutter Maintenance Yard Maintenance Area 0007		A	12.07			
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles
Earthen Levee						
Encroachments						3.30 0.03
Slope Stability		0.38		0.38	3.15%	
Erosion / Bank Caving		0.02		0.02	0.17%	
LMA Totals:		0.40	0.00	0.40	3.31%	3.30 0.03

MA0009		Overall LMA Rating	Total LMA Miles			
Sacramento Maintenance Yard Maintenance Area 0009		M	19.61			
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles
Earthen Levee						
Vegetation		0.14		0.14	0.71%	
Trim / Thin Trees		0.04		0.04	0.20%	
Encroachments		1.80		1.80	9.18%	3.76 1.11
Animal Control		0.01		0.01	0.05%	
Erosion / Bank Caving		0.01		0.01	0.05%	
Supplemental						
USACE Erosion Survey		0.13	0.07	0.41	2.09%	
LMA Totals:		2.13	0.07	2.41	12.29%	3.76 1.11

MA0012		Overall LMA Rating	Total LMA Miles			
Sutter Maintenance Yard Maintenance Area 0012		A	11.31			
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles
No Items						
LMA Totals:		0.00	0.00	0.00	0.00%	0.00 0.00

MA0013		Overall LMA Rating	Total LMA Miles	* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.		
Sutter Maintenance Yard Maintenance Area 0013		M *	41.97			
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles
Earthen Levee						
Trim / Thin Trees		0.03		0.03	0.07%	
Encroachments		0.16		0.16	0.38%	0.01
Animal Control		0.01		0.01	0.02%	
Erosion / Bank Caving		0.37	0.06	0.61	1.45%	
Supplemental						
USACE Erosion Survey		0.39		0.39	0.93%	
LMA Totals:		0.96	0.06	1.20	2.86% *	0.01 0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 01 Cherokee Canal	Overall Unit Rating	Total Unit Miles				
MA0013	A	18.87				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Trim / Thin Trees	0.03		0.03	0.16%		
Encroachments	0.04		0.04	0.21%		
<i>Unit Totals:</i>	0.07	0.00	0.07	0.37%	0.00	0.00
Unit No. 02 Cherokee Canal	Overall Unit Rating	Total Unit Miles	* Overall Unit Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall Unit Rating is M instead of A.			
MA0013	M *	23.10				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments	0.12		0.12	0.52%	0.01	
Animal Control	0.01		0.01	0.04%		
Erosion / Bank Caving	0.37	0.06	0.61	2.64%		
<i>Supplemental</i>						
USACE Erosion Survey	0.39		0.39	1.69%		
<i>Unit Totals:</i>	0.89	0.06	1.13	4.89% *	0.01	0.00
MA0016	Overall LMA Rating	Total LMA Miles				
Sutter Maintenance Yard Maintenance Area 0016	M	4.09				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					0.28	0.04
Animal Control	0.06		0.06	1.47%		
Slope Stability	0.68		0.68	16.63%		
<i>LMA Totals:</i>	0.74	0.00	0.74	18.09%	0.28	0.04
NA0001	Overall LMA Rating	Total LMA Miles				
American River Flood Control District	A	33.24				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.04		0.04	0.12%		
Encroachments	0.14		0.14	0.42%	2.13	2.43
Animal Control	0.04		0.04	0.12%		
<i>Supplemental</i>						
USACE Erosion Survey	0.11		0.11	0.33%		
<i>LMA Totals:</i>	0.33	0.00	0.33	0.99%	2.13	2.43

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 01 Arcade Creek	Overall Unit Rating	Total Unit Miles				
NA0001	A	2.10				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					0.08	0.21
Animal Control	0.01		0.01	0.48%		
<i>Unit Totals:</i>	0.01	0.00	0.01	0.48%	0.08	0.21
Unit No. 02 Natomas E Canal	Overall Unit Rating	Total Unit Miles				
NA0001	A	3.95				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
Unit No. 03 American River	Overall Unit Rating	Total Unit Miles				
NA0001	A	2.78				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
Unit No. 04 American River	Overall Unit Rating	Total Unit Miles				
NA0001	A	10.97				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.04		0.04	0.37%		
Encroachments	0.14		0.14	1.28%	1.26	1.20
Animal Control	0.03		0.03	0.27%		
<i>Supplemental</i>						
USACE Erosion Survey	0.11		0.11	1.00%		
<i>Unit Totals:</i>	0.32	0.00	0.32	2.92%	1.26	1.20
Unit No. 05 Sacramento River	Overall Unit Rating	Total Unit Miles				
NA0001	A	0.40				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					0.11	
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.11	0.00
Unit No. 06 Linda Creek	Overall Unit Rating	Total Unit Miles				
NA0001	A	1.30				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 07 Arcade Creek	Overall Unit Rating	Total Unit Miles				
NA0001	A	1.92				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					0.07	0.19
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.07	0.19
Unit No. 08 Magpie Creek Diversion	Overall Unit Rating	Total Unit Miles				
NA0001	A	1.43				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					0.41	
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.41	0.00
Unit No. 09 American River	Overall Unit Rating	Total Unit Miles				
NA0001	A	4.32				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					0.09	0.13
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.09	0.13
Unit No. 10 American River	Overall Unit Rating	Total Unit Miles				
NA0001	A	3.34				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					0.11	0.70
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.11	0.70
Unit No. 11 New Linda Creek	Overall Unit Rating	Total Unit Miles				
NA0001	A	0.73				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
NA0002	Overall LMA Rating	Total LMA Miles				
Not Inspected; 2009 Data	A	19.32				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Trim / Thin Trees	0.49		0.49	2.54%		
Encroachments					0.23	0.05
<i>LMA Totals:</i>	0.49	0.00	0.49	2.54%	0.23	0.05

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 01 Georgiana Slough	Overall Unit Rating	Total Unit Miles				
NA0002 Not Inspected; 2009 Data	A	6.02				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					0.10	
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.10	0.00
Unit No. 02 Sacramento River	Overall Unit Rating	Total Unit Miles				
NA0002 Not Inspected; 2009 Data	A	13.30				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Trim / Thin Trees	0.49		0.49	3.68%		
Encroachments					0.13	0.05
<i>Unit Totals:</i>	0.49	0.00	0.49	3.68%	0.13	0.05
NA0003	Overall LMA Rating	Total LMA Miles				
Not Inspected; 2009 Data	A	24.71				
Butte County Public Works						
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments	0.09		0.09	0.36%	0.07	0.55
Animal Control	0.09		0.09	0.36%		
Slope Stability	0.01		0.01	0.04%		
<i>LMA Totals:</i>	0.19	0.00	0.19	0.77%	0.07	0.55

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 01 Mud Creek	Overall Unit Rating	Total Unit Miles				
NA0003 Not Inspected; 2009 Data	A	7.29				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments	0.07		0.07	0.96%	0.07	0.05
Animal Control	0.08		0.08	1.10%		
<i>Unit Totals:</i>	0.15	0.00	0.15	2.06%	0.07	0.05

Unit No. 02 Mud Creek	Overall Unit Rating	Total Unit Miles				
NA0003 Not Inspected; 2009 Data	A	8.20				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments	0.02		0.02	0.24%		0.32
Animal Control	0.01		0.01	0.12%		
<i>Unit Totals:</i>	0.03	0.00	0.03	0.37%	0.00	0.32

Unit No. 02A Channel Slough	Overall Unit Rating	Total Unit Miles				
NA0003 Not Inspected; 2009 Data	A	0.30				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

Unit No. 03 Sycamore and Sheep Hollow Creeks	Overall Unit Rating	Total Unit Miles				
NA0003 Not Inspected; 2009 Data	A	4.13				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Slope Stability	0.01		0.01	0.24%		
<i>Unit Totals:</i>	0.01	0.00	0.01	0.24%	0.00	0.00

Unit No. 04 Sycamore and Dry Creeks	Overall Unit Rating	Total Unit Miles				
NA0003 Not Inspected; 2009 Data	A	2.94				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments						0.18
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.18

Unit No. 05 Big Chico Diversion	Overall Unit Rating	Total Unit Miles				
NA0003 Not Inspected; 2009 Data	A	1.85				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

NA0004	Overall LMA Rating	Total LMA Miles				
Marysville Levee Commission	A	11.38				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	1.10		1.10	9.67%		
Encroachments					0.01	0.01
LMA Totals:	1.10	0.00	1.10	9.67%	0.01	0.01
Unit No. 01 Simmerly Slough	Overall Unit Rating	Total Unit Miles				
NA0004	A	3.25				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
Unit Totals:	0.00	0.00	0.00	0.00%	0.00	0.00
Unit No. 02 Feather River	Overall Unit Rating	Total Unit Miles				
NA0004	U	1.27				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	0.43		0.43	33.86%		
Unit Totals:	0.43	0.00	0.43	33.86%	0.00	0.00
Unit No. 03 Yuba River	Overall Unit Rating	Total Unit Miles				
NA0004	A	6.86				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	0.67		0.67	9.77%		
Encroachments					0.01	0.01
Unit Totals:	0.67	0.00	0.67	9.77%	0.01	0.01
NA0005	Overall LMA Rating	Total LMA Miles				
City of Sacramento	A	3.63				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Encroachments	0.02		0.02	0.55%	0.80	
Supplemental						
USACE Erosion Survey	0.07		0.07	1.93%		
LMA Totals:	0.09	0.00	0.09	2.48%	0.80	0.00
NA0006	Overall LMA Rating	Total LMA Miles				
Eastern Honcut Creek	U	1.50				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	2.94		2.94	196.00%		
Crown Surface / Depressions / Rutting	0.67		0.67	44.67%		
LMA Totals:	3.61	0.00	3.61	240.67%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

NA0008	Overall LMA Rating	Total LMA Miles				
Knights Landing Ridge Drainage District	U	12.57				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	0.07		0.07	0.56%		
Trim / Thin Trees	0.01		0.01	0.08%		
Encroachments	0.25		0.25	1.99%	0.62	0.07
Animal Control	0.04		0.04	0.32%		
Supplemental						
USACE Erosion Survey	2.27		2.27	18.06%		
LMA Totals:	2.64	0.00	2.64	21.00%	0.62	0.07

Unit No. 01 Knights Landing Ridge Cut	Overall Unit Rating	Total Unit Miles				
NA0008	A	6.43				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	0.01		0.01	0.16%		
Trim / Thin Trees	0.01		0.01	0.16%		
Encroachments	0.25		0.25	3.89%		
Animal Control	0.04		0.04	0.62%		
Supplemental						
USACE Erosion Survey	0.26		0.26	4.04%		
Unit Totals:	0.57	0.00	0.57	8.87%	0.00	0.00

Unit No. 02 Knights Landing Ridge Cut	Overall Unit Rating	Total Unit Miles				
NA0008	U	6.14				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	0.06		0.06	0.98%		
Encroachments					0.62	0.07
Supplemental						
USACE Erosion Survey	2.01		2.01	32.74%		
Unit Totals:	2.07	0.00	2.07	33.71%	0.62	0.07

NA0012	Overall LMA Rating	Total LMA Miles				
Solano County Public Works Mellin Levee	U	0.59				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	0.11		0.11	18.64%		
Encroachments	0.01		0.01	1.70%	0.77	
Slope Stability	0.01		0.01	1.70%		
LMA Totals:	0.13	0.00	0.13	22.03%	0.77	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

NA0014	Overall LMA Rating	Total LMA Miles				
Murphy Slough at M&T Ranch						
	U	0.78				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	0.50		0.50	64.10%		
LMA Totals:	0.50	0.00	0.50	64.10%	0.00	0.00

NA0016	Overall LMA Rating	Total LMA Miles	* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.			
Sacramento River West Side Levee District						
	M *	50.21				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	0.09		0.09	0.18%		
Trim / Thin Trees	0.03		0.03	0.06%		
Encroachments	0.12	0.01	0.16	0.32%	3.29	0.01
Animal Control	0.22		0.22	0.44%		
Erosion / Bank Caving	0.02		0.02	0.04%		
Crown Surface / Depressions / Rutting		0.01	0.04	0.08%		
Supplemental						
USACE Erosion Survey	0.18		0.18	0.36%		
LMA Totals:	0.66	0.02	0.74	1.47% *	3.29	0.01

NA0018	Overall LMA Rating	Total LMA Miles				
California Department of Fish and Game Shea Levee	A	0.30				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
No Items						
LMA Totals:	0.00	0.00	0.00	0.00%	0.00	0.00

NA0019	Overall LMA Rating	Total LMA Miles				
Tehama County Flood Control and Water Conservation District			A	13.64		
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	0.62		0.62	4.55%		
Encroachments	0.19		0.19	1.39%	0.09	
Animal Control	0.02		0.02	0.15%		
Slope Stability	0.28		0.28	2.05%		
Erosion / Bank Caving	0.02		0.02	0.15%		
Supplemental						
USACE Erosion Survey	0.07		0.07	0.51%		
LMA Totals:	1.20	0.00	1.20	8.80%	0.09	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 01 Deer Creek		Overall Unit Rating	Total Unit Miles				
NA0019		A	4.11				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Encroachments		0.04		0.04	0.97%	0.02	
Slope Stability		0.12		0.12	2.92%		
Erosion / Bank Caving		0.01		0.01	0.24%		
<i>Supplemental</i>							
USACE Erosion Survey		0.02		0.02	0.49%		
<i>Unit Totals:</i>		0.19	0.00	0.19	4.62%	0.02	0.00

Unit No. 02 Deer Creek		Overall Unit Rating	Total Unit Miles				
NA0019		A	1.50				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Encroachments		0.02		0.02	1.33%	0.01	
<i>Supplemental</i>							
USACE Erosion Survey		0.05		0.05	3.33%		
<i>Unit Totals:</i>		0.07	0.00	0.07	4.67%	0.01	0.00

Unit No. 04 Elder Creek		Overall Unit Rating	Total Unit Miles				
NA0019		A	4.07				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Encroachments		0.02		0.02	0.49%		
Animal Control		0.01		0.01	0.25%		
Slope Stability		0.16		0.16	3.93%		
<i>Unit Totals:</i>		0.19	0.00	0.19	4.67%	0.00	0.00

Unit No. 05 Elder Creek		Overall Unit Rating	Total Unit Miles				
NA0019		M	3.96				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		0.62		0.62	15.66%		
Encroachments		0.11		0.11	2.78%	0.06	
Animal Control		0.01		0.01	0.25%		
Erosion / Bank Caving		0.01		0.01	0.25%		
<i>Unit Totals:</i>		0.75	0.00	0.75	18.94%	0.06	0.00

NA0020		Overall LMA Rating	Total LMA Miles				
Sutter Maintenance Yard East-West Interceptor		U	4.76				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		3.17		3.17	66.60%		
Encroachments		0.24		0.24	5.04%	0.02	
Erosion / Bank Caving		0.39	0.04	0.55	11.55%		
<i>LMA Totals:</i>		3.80	0.04	3.96	83.19%	0.02	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 01 West Levee	Overall Unit Rating	Total Unit Miles	* Overall Unit Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall Unit Rating is M instead of A.			
NA0020	M *	1.75				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					0.02	
Erosion / Bank Caving		0.04	0.16	9.14%		
<i>Unit Totals:</i>	0.00	0.04	0.16	9.14% *	0.02	0.00
Unit No. 02 East Levee	Overall Unit Rating	Total Unit Miles				
NA0020	U	3.01				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	3.17		3.17	105.32%		
Encroachments	0.24		0.24	7.97%		
Erosion / Bank Caving	0.39		0.39	12.96%		
<i>Unit Totals:</i>	3.80	0.00	3.80	126.25%	0.00	0.00
NA0021	Overall LMA Rating	Total LMA Miles				
Yolo County Planning Resources and Public Works	U	0.29				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.51		0.51	175.86%		
Trim / Thin Trees	0.09		0.09	31.03%		
<i>LMA Totals:</i>	0.60	0.00	0.60	206.90%	0.00	0.00
NA0022	Overall LMA Rating	Total LMA Miles				
Yolo County Service Area 6	A	5.97				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.44		0.44	7.37%		
Trim / Thin Trees	0.02		0.02	0.34%		
Encroachments	0.06		0.06	1.01%	0.44	0.14
Animal Control	0.03		0.03	0.50%		
<i>LMA Totals:</i>	0.55	0.00	0.55	9.21%	0.44	0.14
RD0003	Overall LMA Rating	Total LMA Miles	* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.			
Reclamation District No. 0003 Grand Island	M *	28.65				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	1.12	0.03	1.24	4.33%		
Trim / Thin Trees	0.67	0.04	0.83	2.90%		
Encroachments	0.10		0.10	0.35%	3.54	0.87
Erosion / Bank Caving	0.02		0.02	0.07%		
<i>Supplemental</i>						
USACE Erosion Survey	0.20	0.07	0.48	1.68%		
<i>LMA Totals:</i>	2.11	0.14	2.67	9.32% *	3.54	0.87

**Flood Control Project Maintenance
Levee Inspections**

**Fall 2010 Levee Maintenance Deficiency Summary Report
Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey**

Sacramento River Basin (cont.)

Unit No. 01 Left Bank Steamboat Slough		Overall Unit Rating	Total Unit Miles				
RD0003		M	11.03				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		0.71		0.71	6.44%		
Trim / Thin Trees		0.25	0.02	0.33	2.99%		
Encroachments		0.06		0.06	0.54%	2.12	0.27
Erosion / Bank Caving		0.01		0.01	0.09%		
<i>Supplemental</i>							
USACE Erosion Survey		0.12	0.07	0.40	3.63%		
<i>Unit Totals:</i>		1.15	0.09	1.51	13.69%	2.12	0.27

Unit No. 02 Right Bank Sacramento River		Overall Unit Rating	Total Unit Miles	* Overall Unit Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall Unit Rating is M instead of A.			
RD0003		M *	17.62				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		0.41	0.03	0.53	3.01%		
Trim / Thin Trees		0.42	0.02	0.50	2.84%		
Encroachments		0.04		0.04	0.23%	1.42	0.60
Erosion / Bank Caving		0.01		0.01	0.06%		
<i>Supplemental</i>							
USACE Erosion Survey		0.08		0.08	0.45%		
<i>Unit Totals:</i>		0.96	0.05	1.16	6.58% *	1.42	0.60

RD0010 Not Inspected; 2009 Data		Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0010 Honcut		A	21.93				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		0.44		0.44	2.01%		
Trim / Thin Trees		0.04		0.04	0.18%		
Encroachments		0.03		0.03	0.14%	0.01	
Animal Control		0.08		0.08	0.37%		
<i>LMA Totals:</i>		0.59	0.00	0.59	2.69%	0.01	0.00

**Flood Control Project Maintenance
Levee Inspections**

**Fall 2010 Levee Maintenance Deficiency Summary Report
Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey**

Sacramento River Basin (cont.)

Unit No. 01 Simmerly Slough	Overall Unit Rating	Total Unit Miles				
RD0010 Not Inspected; 2009 Data	A	7.68				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.05		0.05	0.65%		
Trim / Thin Trees	0.02		0.02	0.26%		
<i>Unit Totals:</i>	0.07	0.00	0.07	0.91%	0.00	0.00
Unit No. 02 Feather River	Overall Unit Rating	Total Unit Miles				
RD0010 Not Inspected; 2009 Data	A	11.24				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.38		0.38	3.38%		
Trim / Thin Trees	0.01		0.01	0.09%		
Encroachments	0.03		0.03	0.27%	0.01	
Animal Control	0.07		0.07	0.62%		
<i>Unit Totals:</i>	0.49	0.00	0.49	4.36%	0.01	0.00
Unit No. 03 Honcut Creek	Overall Unit Rating	Total Unit Miles				
RD0010 Not Inspected; 2009 Data	A	3.01				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.01		0.01	0.33%		
Trim / Thin Trees	0.01		0.01	0.33%		
Animal Control	0.01		0.01	0.33%		
<i>Unit Totals:</i>	0.03	0.00	0.03	1.00%	0.00	0.00
RD0070 Not Inspected; 2009 Data	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0070 Meridian	A	23.57				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					0.16	0.03
<i>Supplemental</i>						
USACE Erosion Survey	0.29		0.29	1.23%		
<i>LMA Totals:</i>	0.29	0.00	0.29	1.23%	0.16	0.03

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 01 Sutter Bypass	Overall Unit Rating	Total Unit Miles				
RD0070 Not Inspected; 2009 Data	A	8.00				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
No Items					PO Miles	CO Miles
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

Unit No. 02 Sacramento River	Overall Unit Rating	Total Unit Miles				
RD0070 Not Inspected; 2009 Data	A	15.57				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
No Items					PO Miles	CO Miles
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

<i>Earthen Levee</i>						
Encroachments					0.16	0.03
<i>Supplemental</i>						
USACE Erosion Survey	0.29		0.29	1.86%		
<i>Unit Totals:</i>	0.29	0.00	0.29	1.86%	0.16	0.03

RD0108 Not Inspected; 2009 Data Reclamation District No. 0108 River Farms	Overall LMA Rating	Total LMA Miles				
	A	20.59				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
No Items					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.02		0.02	0.10%		
Trim / Thin Trees	0.89		0.89	4.32%		
Encroachments					0.72	
Animal Control	0.06		0.06	0.29%		
Cracking	0.03		0.03	0.15%		
<i>LMA Totals:</i>	1.00	0.00	1.00	4.86%	0.72	0.00

RD0150 Reclamation District No. 0150 Merrit Island	Overall LMA Rating	Total LMA Miles	* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.			
	M *	18.07				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
No Items					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.09		0.09	0.50%		
Trim / Thin Trees	0.51		0.51	2.82%		
Encroachments	0.28		0.28	1.55%	1.28	0.30
Slope Stability	0.07		0.07	0.39%		
Erosion / Bank Caving	0.11		0.11	0.61%		
Crown Surface / Depressions / Rutting	0.04		0.04	0.22%		
<i>Interior Drainage & Piping Systems</i>						
Metal Pipes	0.01		0.01	0.06%		
<i>Supplemental</i>						
USACE Erosion Survey	0.12	0.03	0.24	1.33%		
<i>LMA Totals:</i>	1.23	0.03	1.35	7.47% *	1.28	0.30

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 01 Sutter Slough	Overall Unit Rating	Total Unit Miles				
RD0150	A	0.54				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments	0.01		0.01	1.85%		
<i>Unit Totals:</i>	0.01	0.00	0.01	1.85%	0.00	0.00
Unit No. 02 Sacramento River	Overall Unit Rating	Total Unit Miles				
RD0150	M	7.95				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.05		0.05	0.63%		
Trim / Thin Trees	0.44		0.44	5.54%		
Encroachments	0.18		0.18	2.26%	0.56	0.29
Slope Stability	0.04		0.04	0.50%		
Erosion / Bank Caving	0.02		0.02	0.25%		
<i>Interior Drainage & Piping Systems</i>						
Metal Pipes	0.01		0.01	0.13%		
<i>Supplemental</i>						
USACE Erosion Survey	0.11	0.03	0.23	2.89%		
<i>Unit Totals:</i>	0.85	0.03	0.97	12.20%	0.56	0.29
Unit No. 03 Elk Slough	Overall Unit Rating	Total Unit Miles				
RD0150	A	9.58				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.04		0.04	0.42%		
Trim / Thin Trees	0.07		0.07	0.73%		
Encroachments	0.09		0.09	0.94%	0.72	0.01
Slope Stability	0.03		0.03	0.31%		
Erosion / Bank Caving	0.09		0.09	0.94%		
Crown Surface / Depressions / Rutting	0.04		0.04	0.42%		
<i>Supplemental</i>						
USACE Erosion Survey	0.01		0.01	0.10%		
<i>Unit Totals:</i>	0.37	0.00	0.37	3.86%	0.72	0.01
RD0307	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0307 Lisbon	U	6.65				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.81	0.09	1.17	17.59%		
Trim / Thin Trees	3.86	0.05	4.06	61.05%		
Encroachments	0.04		0.04	0.60%	0.80	0.04
Animal Control	0.08		0.08	1.20%		
<i>LMA Totals:</i>	4.79	0.14	5.35	80.45%	0.80	0.04

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

RD0341 Reclamation District No. 0341 Sherman Island	Overall LMA Rating	Total LMA Miles				
	A	9.62				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
No Items					PO Miles	CO Miles
<i>LMA Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

Unit No. 01 Threemile Slough RD0341 Not Inspected; 2009 Data	Overall Unit Rating	Total Unit Miles				
	A	3.34				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
No Items					PO Miles	CO Miles
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

Unit No. 02 Sacramento River RD0341 Not Inspected; 2009 Data	Overall Unit Rating	Total Unit Miles				
	A	6.28				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
No Items					PO Miles	CO Miles
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

RD0349 Reclamation District No. 0349 Sutter Island	Overall LMA Rating	Total LMA Miles				
	U	12.49				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.20		0.20	1.60%		
Trim / Thin Trees	2.39		2.39	19.14%		
Encroachments	0.11		0.11	0.88%	0.79	0.22
<i>LMA Totals:</i>	2.70	0.00	2.70	21.62%	0.79	0.22

**Flood Control Project Maintenance
Levee Inspections**

**Fall 2010 Levee Maintenance Deficiency Summary Report
Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey**

Sacramento River Basin (cont.)

Unit No. 01 Sacramento River	Overall Unit Rating	Total Unit Miles				
RD0349	U	1.59				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.03		0.03	1.89%		
Trim / Thin Trees	0.91		0.91	57.23%		
Encroachments					0.47	0.04
<i>Unit Totals:</i>	0.94	0.00	0.94	59.12%	0.47	0.04
Unit No. 02 Steamboat Slough	Overall Unit Rating	Total Unit Miles				
RD0349	A	4.35				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.17		0.17	3.91%		
Encroachments	0.09		0.09	2.07%	0.32	0.06
<i>Unit Totals:</i>	0.26	0.00	0.26	5.98%	0.32	0.06
Unit No. 03 Sutter Slough	Overall Unit Rating	Total Unit Miles				
RD0349	U	6.55				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Trim / Thin Trees	1.48		1.48	22.60%		
Encroachments	0.02		0.02	0.31%		0.12
<i>Unit Totals:</i>	1.50	0.00	1.50	22.90%	0.00	0.12
RD0369	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0369 Libby McNeil	A	0.80				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.01		0.01	1.25%		
Encroachments					0.08	0.33
<i>LMA Totals:</i>	0.01	0.00	0.01	1.25%	0.08	0.33
RD0501	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0501 Ryer Island	U	20.48				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	9.41	1.50	15.41	75.24%		
Trim / Thin Trees	1.76	0.20	2.56	12.50%		
Encroachments	0.02		0.02	0.10%	0.65	0.40
Animal Control	0.51		0.51	2.49%		
Erosion / Bank Caving	0.06		0.06	0.29%		
Cracking	0.01		0.01	0.05%		
<i>Supplemental</i>						
USACE Erosion Survey		0.04	0.16	0.78%		
<i>LMA Totals:</i>	11.77	1.74	18.73	91.46%	0.65	0.40

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 01 Steamboat Slough		Overall Unit Rating	Total Unit Miles				
RD0501		U	6.76				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		6.55	0.79	9.71	143.64%		
Trim / Thin Trees		1.26	0.04	1.42	21.01%		
Encroachments		0.01		0.01	0.15%	0.51	
Animal Control		0.51		0.51	7.54%		
Erosion / Bank Caving		0.06		0.06	0.89%		
<i>Unit Totals:</i>		8.39	0.83	11.71	173.22%	0.51	0.00

Unit No. 02 Cache Slough		Overall Unit Rating	Total Unit Miles				
RD0501		U	3.57				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		2.13		2.13	59.66%		
Trim / Thin Trees		0.03		0.03	0.84%		
Encroachments						0.08	0.29
<i>Supplemental</i>							
USACE Erosion Survey			0.04	0.16	4.48%		
<i>Unit Totals:</i>		2.16	0.04	2.32	64.99%	0.08	0.29

Unit No. 03 Miner Slough		Overall Unit Rating	Total Unit Miles				
RD0501		M	7.82				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		0.58		0.58	7.42%		
Trim / Thin Trees		0.27	0.13	0.79	10.10%		
Encroachments						0.05	
Cracking		0.01		0.01	0.13%		
<i>Unit Totals:</i>		0.86	0.13	1.38	17.65%	0.05	0.00

Unit No. 04 Sutter Slough		Overall Unit Rating	Total Unit Miles				
RD0501		U	2.33				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		0.15	0.71	2.99	128.33%		
Trim / Thin Trees		0.20	0.03	0.32	13.73%		
Encroachments		0.01		0.01	0.43%	0.01	0.11
<i>Unit Totals:</i>		0.36	0.74	3.32	142.49%	0.01	0.11

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

RD0536	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0536 Egbert						
	U	10.63				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	1.03		1.03	9.69%		
Encroachments	0.05		0.05	0.47%		
Erosion / Bank Caving	0.01		0.01	0.09%		
Crown Surface / Depressions / Rutting	2.38		2.38	22.39%		
LMA Totals:	3.47	0.00	3.47	32.64%	0.00	0.00
Unit No. 01 Lindsey Slough	Overall Unit Rating	Total Unit Miles				
RD0536						
	M	5.66				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	0.36		0.36	6.36%		
Crown Surface / Depressions / Rutting	0.33		0.33	5.83%		
Unit Totals:	0.69	0.00	0.69	12.19%	0.00	0.00
Unit No. 02 Yolo Bypass	Overall Unit Rating	Total Unit Miles				
RD0536						
	U	4.97				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	0.67		0.67	13.48%		
Encroachments	0.05		0.05	1.01%		
Erosion / Bank Caving	0.01		0.01	0.20%		
Crown Surface / Depressions / Rutting	2.05		2.05	41.25%		
Unit Totals:	2.78	0.00	2.78	55.94%	0.00	0.00
RD0537	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0537 Lovdal						
	U	5.95				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	1.39		1.39	23.36%		
Trim / Thin Trees	0.06		0.06	1.01%		
Encroachments	0.06		0.06	1.01%	0.08	0.19
Erosion / Bank Caving	0.01		0.01	0.17%		
Supplemental						
USACE Erosion Survey	0.03	0.04	0.19	3.19%		
LMA Totals:	1.55	0.04	1.71	28.74%	0.08	0.19

**Flood Control Project Maintenance
Levee Inspections**

**Fall 2010 Levee Maintenance Deficiency Summary Report
Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey**

Sacramento River Basin (cont.)

Unit No. 01 Sacramento River	Overall Unit Rating	Total Unit Miles				
RD0537	M	4.76				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.24		0.24	5.04%		
Trim / Thin Trees	0.04		0.04	0.84%		
Encroachments	0.06		0.06	1.26%	0.08	0.19
Erosion / Bank Caving	0.01		0.01	0.21%		
<i>Supplemental</i>						
USACE Erosion Survey	0.03	0.04	0.19	3.99%		
<i>Unit Totals:</i>	0.38	0.04	0.54	11.34%	0.08	0.19

Unit No. 02 Yolo Bypass	Overall Unit Rating	Total Unit Miles				
RD0537	U	1.19				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	1.15		1.15	96.64%		
Trim / Thin Trees	0.02		0.02	1.68%		
<i>Unit Totals:</i>	1.17	0.00	1.17	98.32%	0.00	0.00

RD0551 Not Inspected; 2009 Data	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0551 Pierson	A	6.84				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments	0.03		0.03	0.44%	0.01	0.08
<i>LMA Totals:</i>	0.03	0.00	0.03	0.44%	0.01	0.08

RD0554	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0554 Walnut Grove	U	1.09				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.14		0.14	12.84%		
Trim / Thin Trees	0.01		0.01	0.92%		
Encroachments	0.01		0.01	0.92%	0.02	
Animal Control	0.02		0.02	1.84%		
<i>Supplemental</i>						
USACE Erosion Survey		0.09	0.36	33.03%		
<i>LMA Totals:</i>	0.18	0.09	0.54	49.54%	0.02	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

RD0556	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0556 Upper Andrus	U	11.19				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	4.99	1.39	10.55	94.28%		
Trim / Thin Trees	0.02	0.33	1.34	11.97%		
Encroachments	0.09	0.04	0.25	2.23%	1.74	0.39
Slope Stability		0.25	1.00	8.94%		
Supplemental						
USACE Erosion Survey	0.37	0.14	0.93	8.31%		
LMA Totals:	5.47	2.15	14.07	125.74%	1.74	0.39

Unit No. 01 Georgiana Slough	Overall Unit Rating	Total Unit Miles				
RD0556	U	5.47				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	1.41	1.39	6.97	127.42%		
Trim / Thin Trees	0.02	0.33	1.34	24.50%		
Encroachments	0.09	0.04	0.25	4.57%	1.05	0.19
Slope Stability		0.25	1.00	18.28%		
Unit Totals:	1.52	2.01	9.56	174.77%	1.05	0.19

Unit No. 02 Sacramento River	Overall Unit Rating	Total Unit Miles				
RD0556	U	5.72				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	3.58		3.58	62.59%		
Encroachments					0.69	0.20
Supplemental						
USACE Erosion Survey	0.37	0.14	0.93	16.26%		
Unit Totals:	3.95	0.14	4.51	78.85%	0.69	0.20

RD0563	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0563 Tyler Island	U	12.38				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	0.09	0.11	0.53	4.28%		
Trim / Thin Trees	0.21	0.05	0.41	3.31%		
Encroachments	0.24	0.01	0.28	2.26%	0.07	0.12
Animal Control	0.02		0.02	0.16%		
Slope Stability	0.01	0.01	0.05	0.40%		
Erosion / Bank Caving		0.01	0.04	0.32%		
Crown Surface / Depressions / Rutting		0.01	0.04	0.32%		
Supplemental						
USACE Erosion Survey	2.72	0.35	4.12	33.28%		
LMA Totals:	3.29	0.55	5.49	44.35%	0.07	0.12

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

RD0755	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0755 Randall	U	1.86				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.02		0.02	1.08%		
Encroachments					0.10	
Animal Control	1.27		1.27	68.28%		
<i>LMA Totals:</i>	1.29	0.00	1.29	69.36%	0.10	0.00

RD0765	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0765 Glide	U	1.74				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.13	0.03	0.25	14.37%		
Trim / Thin Trees	0.63	0.20	1.43	82.18%		
Encroachments	0.01		0.01	0.58%	0.11	0.03
<i>LMA Totals:</i>	0.77	0.23	1.69	97.13%	0.11	0.03

RD0784	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0784 Plumas Lake	A	38.43				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.32		0.32	0.83%		
Encroachments					1.61	0.01
<i>LMA Totals:</i>	0.32	0.00	0.32	0.83%	1.61	0.01

**Flood Control Project Maintenance
Levee Inspections**

**Fall 2010 Levee Maintenance Deficiency Summary Report
Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey**

Sacramento River Basin (cont.)

Unit No. 01 Yuba River	Overall Unit Rating	Total Unit Miles				
RD0784 Not Inspected; 2009 Data	A	2.22				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
No Items					PO Miles	CO Miles
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

Unit No. 02 Feather River	Overall Unit Rating	Total Unit Miles				
RD0784 Not Inspected; 2009 Data	A	13.64				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
No Items					PO Miles	CO Miles
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

Unit No. 03 Bear River	Overall Unit Rating	Total Unit Miles				
RD0784 Not Inspected; 2009 Data	A	4.73				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
<i>Earthen Levee</i>					PO Miles	CO Miles
Encroachments					0.01	
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.01	0.00

Unit No. 04 Interceptor Canal	Overall Unit Rating	Total Unit Miles				
RD0784 Not Inspected; 2009 Data	A	6.35				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
No Items					PO Miles	CO Miles
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

Unit No. 05 Interceptor Canal	Overall Unit Rating	Total Unit Miles				
RD0784 Not Inspected; 2009 Data	A	4.20				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
<i>Earthen Levee</i>					PO Miles	CO Miles
Vegetation	0.32		0.32	7.62%		
Encroachments					1.60	
<i>Unit Totals:</i>	0.32	0.00	0.32	7.62%	1.60	0.00

Unit No. 06 South Dry Creek	Overall Unit Rating	Total Unit Miles				
RD0784 Not Inspected; 2009 Data	A	1.50				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
No Items					PO Miles	CO Miles
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 07 Yuba River		Overall Unit Rating	Total Unit Miles				
RD0784	Not Inspected; 2009 Data	A	3.91				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
Earthen Levee						PO Miles	CO Miles
Encroachments							0.01
Unit Totals:		0.00	0.00	0.00	0.00%	0.00	0.01

Unit No. 08 Three Rivers		Overall Unit Rating	Total Unit Miles				
RD0784	Not Inspected; 2009 Data	A	1.88				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
No Items						PO Miles	CO Miles
Unit Totals:		0.00	0.00	0.00	0.00%	0.00	0.00

RD0785		Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0785 Driver		U	5.61				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
Earthen Levee						PO Miles	CO Miles
Vegetation		5.30		5.30	94.47%		
Encroachments						0.11	
Crown Surface / Depressions / Rutting		2.64		2.64	47.06%		
LMA Totals:		7.94	0.00	7.94	141.53%	0.11	0.00

Unit No. 01 Sacramento River		Overall Unit Rating	Total Unit Miles				
RD0785		A	2.31				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
Earthen Levee						PO Miles	CO Miles
Encroachments						0.11	
Unit Totals:		0.00	0.00	0.00	0.00%	0.11	0.00

Unit No. 02 Yolo Bypass		Overall Unit Rating	Total Unit Miles				
RD0785		U	3.30				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
Earthen Levee						PO Miles	CO Miles
Vegetation		5.30		5.30	160.61%		
Crown Surface / Depressions / Rutting		2.64		2.64	80.00%		
Unit Totals:		7.94	0.00	7.94	240.61%	0.00	0.00

RD0787		Overall LMA Rating	Total LMA Miles				
Not Inspected; 2009 Data Reclamation District No. 0787 Fair		A	4.40				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
Earthen Levee						PO Miles	CO Miles
Encroachments						2.40	
LMA Totals:		0.00	0.00	0.00	0.00%	2.40	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

RD0817	Not Inspected; 2009 Data	Overall LMA Rating	Total LMA Miles			
Reclamation District No. 0817 Carlin		A	9.19			
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles
Earthen Levee						
Vegetation		0.09		0.09	0.98%	
Encroachments						0.06
Crown Surface / Depressions / Rutting		0.17		0.17	1.85%	
LMA Totals:		0.26	0.00	0.26	2.83%	0.06 0.00

Unit No. 01 South Dry Creek		Overall Unit Rating	Total Unit Miles			
RD0817 Not Inspected; 2009 Data		A	3.82			
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles
No Items						
Unit Totals:		0.00	0.00	0.00	0.00%	0.00 0.00

Unit No. 02 Bear River		Overall Unit Rating	Total Unit Miles			
RD0817 Not Inspected; 2009 Data		A	3.87			
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles
Earthen Levee						
Vegetation		0.05		0.05	1.29%	
Encroachments						0.06
Unit Totals:		0.05	0.00	0.05	1.29%	0.06 0.00

Unit No. 03 Dry Creek		Overall Unit Rating	Total Unit Miles			
RD0817 Not Inspected; 2009 Data		M	1.50			
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles
Earthen Levee						
Vegetation		0.04		0.04	2.67%	
Crown Surface / Depressions / Rutting		0.17		0.17	11.33%	
Unit Totals:		0.21	0.00	0.21	14.00%	0.00 0.00

RD0827		Overall LMA Rating	Total LMA Miles			
Reclamation District No. 0827 Elkhorn		U	4.19			
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles
Earthen Levee						
Vegetation		0.12		0.12	2.86%	
Trim / Thin Trees		0.13		0.13	3.10%	
Encroachments		0.02		0.02	0.48%	0.24
Animal Control		0.01		0.01	0.24%	
Crown Surface / Depressions / Rutting		1.61		1.61	38.43%	
LMA Totals:		1.89	0.00	1.89	45.11%	0.24 0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 01 Sacramento River	Overall Unit Rating	Total Unit Miles				
RD0827	U	1.35				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.12		0.12	8.89%		
Trim / Thin Trees	0.13		0.13	9.63%		
Encroachments	0.02		0.02	1.48%		
Animal Control	0.01		0.01	0.74%		
<i>Unit Totals:</i>	0.28	0.00	0.28	20.74%	0.00	0.00

Unit No. 02 Yolo Bypass	Overall Unit Rating	Total Unit Miles				
RD0827	U	2.84				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					0.24	
Crown Surface / Depressions / Rutting	1.61		1.61	56.69%		
<i>Unit Totals:</i>	1.61	0.00	1.61	56.69%	0.24	0.00

RD0900	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0900 West Sacramento	M	13.57				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	1.22		1.22	8.99%		
Trim / Thin Trees	0.02		0.02	0.15%		
Encroachments	0.02		0.02	0.15%	3.93	0.01
Slope Stability	0.01		0.01	0.07%		
Cracking	0.01		0.01	0.07%		
<i>Supplemental</i>						
USACE Erosion Survey		0.27	1.08	7.96%		
<i>LMA Totals:</i>	1.28	0.27	2.36	17.39%	3.93	0.01

**Flood Control Project Maintenance
Levee Inspections**

**Fall 2010 Levee Maintenance Deficiency Summary Report
Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey**

Sacramento River Basin (cont.)

Unit No. 01 Sacramento River	Overall Unit Rating	Total Unit Miles				
RD0900	M	7.84				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.35		0.35	4.46%		
Trim / Thin Trees	0.02		0.02	0.26%		
Encroachments	0.01		0.01	0.13%	1.70	0.01
<i>Supplemental</i>						
USACE Erosion Survey		0.27	1.08	13.78%		
<i>Unit Totals:</i>	0.38	0.27	1.46	18.62%	1.70	0.01
Unit No. 02 Yolo Bypass	Overall Unit Rating	Total Unit Miles				
RD0900	M	5.73				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.87		0.87	15.18%		
Encroachments	0.01		0.01	0.18%	2.23	
Slope Stability	0.01		0.01	0.18%		
Cracking	0.01		0.01	0.18%		
<i>Unit Totals:</i>	0.90	0.00	0.90	15.71%	2.23	0.00
RD0999	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0999						
Netherlands	U	32.37				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.20		0.20	0.62%		
Trim / Thin Trees	2.43	0.17	3.11	9.61%		
Encroachments	0.49	0.41	2.13	6.58%	1.47	0.19
Animal Control	1.32		1.32	4.08%		
Crown Surface / Depressions / Rutting	0.73		0.73	2.26%		
Repair Gates	0.01		0.01	0.03%		
<i>Supplemental</i>						
USACE Erosion Survey	0.59	9.44	38.35	118.47%		
<i>LMA Totals:</i>	5.77	10.02	45.85	141.64%	1.47	0.19

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 01 Yolo Bypass		Overall Unit Rating	Total Unit Miles				
RD0999		M	15.43				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Trim / Thin Trees		0.58		0.58	3.76%		
Encroachments		0.07	0.29	1.23	7.97%	0.26	
Animal Control		0.01		0.01	0.07%		
Crown Surface / Depressions / Rutting		0.73		0.73	4.73%		
Repair Gates		0.01		0.01	0.07%		
<i>Supplemental</i>							
USACE Erosion Survey		0.02		0.02	0.13%		
<i>Unit Totals:</i>		1.42	0.29	2.58	16.72%	0.26	0.00

Unit No. 02 Miner Slough		Overall Unit Rating	Total Unit Miles				
RD0999		A	2.32				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		0.03		0.03	1.29%		
Trim / Thin Trees		0.08		0.08	3.45%		
Encroachments		0.01		0.01	0.43%	0.06	0.02
<i>Unit Totals:</i>		0.12	0.00	0.12	5.17%	0.06	0.02

Unit No. 03 Sutter Slough		Overall Unit Rating	Total Unit Miles				
RD0999		U	3.74				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		0.02		0.02	0.54%		
Trim / Thin Trees		0.38	0.02	0.46	12.30%		
Encroachments		0.03	0.01	0.07	1.87%		0.04
<i>Supplemental</i>							
USACE Erosion Survey		0.55		0.55	14.71%		
<i>Unit Totals:</i>		0.98	0.03	1.10	29.41%	0.00	0.04

Unit No. 04 Sacramento River		Overall Unit Rating	Total Unit Miles				
RD0999		U	1.22				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Trim / Thin Trees		0.07	0.13	0.59	48.36%		
Encroachments						0.29	
<i>Supplemental</i>							
USACE Erosion Survey			0.04	0.16	13.11%		
<i>Unit Totals:</i>		0.07	0.17	0.75	61.48%	0.29	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 05 Elk Slough		Overall Unit Rating	Total Unit Miles			
RD0999		U	9.66			
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.15		0.15	1.55%		
Trim / Thin Trees	1.32	0.02	1.40	14.49%		
Encroachments	0.38	0.11	0.82	8.49%	0.86	0.13
Animal Control	1.31		1.31	13.56%		
<i>Supplemental</i>						
USACE Erosion Survey	0.02	9.40	37.62	389.44%		
<i>Unit Totals:</i>	3.18	9.53	41.30	427.54%	0.86	0.13

RD1000		Overall LMA Rating	Total LMA Miles			
Reclamation District No. 1000 Natomas		A	42.48			
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	3.39		3.39	7.98%		
Encroachments					13.29	1.31
<i>Supplemental</i>						
USACE Erosion Survey	0.13		0.13	0.31%		
<i>LMA Totals:</i>	3.52	0.00	3.52	8.29%	13.29	1.31

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 01 Sacramento River	Overall Unit Rating	Total Unit Miles				
RD1000	A	18.60				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					7.90	1.31
<i>Supplemental</i>						
USACE Erosion Survey	0.13		0.13	0.70%		
<i>Unit Totals:</i>	0.13	0.00	0.13	0.70%	7.90	1.31
Unit No. 02 American River	Overall Unit Rating	Total Unit Miles				
RD1000	A	2.33				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					4.66	
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	4.66	0.00
Unit No. 03 Natomas East Canal	Overall Unit Rating	Total Unit Miles				
RD1000	M	17.17				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	3.39		3.39	19.74%		
Encroachments					0.73	
<i>Unit Totals:</i>	3.39	0.00	3.39	19.74%	0.73	0.00
Unit No. 04 Natomas Cross Canal	Overall Unit Rating	Total Unit Miles				
RD1000	A	4.38				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
RD1001	Overall LMA Rating	Total LMA Miles	* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.			
Reclamation District No. 1001 Nicolaus	M *	44.03				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.58		0.58	1.32%		
Encroachments	0.14		0.14	0.32%	2.43	0.05
Slope Stability	0.01		0.01	0.02%		
<i>Supplemental</i>						
USACE Erosion Survey	0.03	0.34	1.39	3.16%		
<i>LMA Totals:</i>	0.76	0.34	2.12	4.81% *	2.43	0.05

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 01 Yankee Slough	Overall Unit Rating	Total Unit Miles				
RD1001	A	4.17				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments	0.01		0.01	0.24%	0.06	0.01
<i>Unit Totals:</i>	0.01	0.00	0.01	0.24%	0.06	0.01
Unit No. 02 Yankee Slough	Overall Unit Rating	Total Unit Miles				
RD1001	A	3.66				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments	0.04		0.04	1.09%	0.03	0.02
<i>Unit Totals:</i>	0.04	0.00	0.04	1.09%	0.03	0.02
Unit No. 03 Bear River	Overall Unit Rating	Total Unit Miles	* Overall Unit Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall Unit Rating is M instead of A.			
RD1001	M *	12.60				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.06		0.06	0.48%		
Encroachments	0.06		0.06	0.48%	0.57	
Slope Stability	0.01		0.01	0.08%		
<i>Supplemental</i>						
USACE Erosion Survey		0.06	0.24	1.90%		
<i>Unit Totals:</i>	0.13	0.06	0.37	2.94% *	0.57	0.00
Unit No. 04 Feather River	Overall Unit Rating	Total Unit Miles				
RD1001	M	13.36				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.51		0.51	3.82%		
Encroachments	0.03		0.03	0.23%	0.04	0.01
<i>Supplemental</i>						
USACE Erosion Survey	0.03	0.28	1.15	8.61%		
<i>Unit Totals:</i>	0.57	0.28	1.69	12.65%	0.04	0.01
Unit No. 05 Natomas Cross Canal	Overall Unit Rating	Total Unit Miles				
RD1001	A	5.44				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					1.70	0.01
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	1.70	0.01

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 06 East Side Canal	Overall Unit Rating	Total Unit Miles				
RD1001	A	4.80				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.01		0.01	0.21%		
Encroachments					0.03	
<i>Unit Totals:</i>	0.01	0.00	0.01	0.21%	0.03	0.00
RD1500	Overall LMA Rating	Total LMA Miles	* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.			
Reclamation District No. 1500 Sutter Basin	M *	54.35				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.24		0.24	0.44%		
Trim / Thin Trees	0.27		0.27	0.50%		
Encroachments	0.10		0.10	0.18%	6.77	0.05
Animal Control	0.10		0.10	0.18%		
Erosion / Bank Caving	0.02		0.02	0.04%		
Crown Surface / Depressions / Rutting	0.01		0.01	0.02%		
<i>Supplemental</i>						
USACE Erosion Survey	1.43	0.21	2.27	4.18%		
<i>LMA Totals:</i>	2.17	0.21	3.01	5.54% *	6.77	0.05
Unit No. 01 Sacramento River	Overall Unit Rating	Total Unit Miles	* Overall Unit Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall Unit Rating is M instead of A.			
RD1500	M *	33.58				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.24		0.24	0.72%		
Trim / Thin Trees	0.27		0.27	0.80%		
Encroachments	0.09		0.09	0.27%	6.77	0.05
Animal Control	0.08		0.08	0.24%		
Erosion / Bank Caving	0.02		0.02	0.06%		
<i>Supplemental</i>						
USACE Erosion Survey	1.43	0.21	2.27	6.76%		
<i>Unit Totals:</i>	2.13	0.21	2.97	8.84% *	6.77	0.05
Unit No. 02 Sutter Bypass	Overall Unit Rating	Total Unit Miles				
RD1500	A	20.77				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments	0.01		0.01	0.05%		
Animal Control	0.02		0.02	0.10%		
Crown Surface / Depressions / Rutting	0.01		0.01	0.05%		
<i>Unit Totals:</i>	0.04	0.00	0.04	0.19%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

RD1600	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 1600 Mull			U	14.73		
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Vegetation	2.55		2.55	17.31%		
Trim / Thin Trees	0.01	0.01	0.05	0.34%		
Encroachments	0.04		0.04	0.27%	0.01	0.08
Animal Control	0.04		0.04	0.27%		
Erosion / Bank Caving	1.02		1.02	6.93%		
LMA Totals:	3.66	0.01	3.70	25.12%	0.01	0.08

Unit No. 01 Sacramento River	Overall Unit Rating	Total Unit Miles				
RD1600			M	10.51		
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Vegetation	1.63		1.63	15.51%		
Trim / Thin Trees	0.01	0.01	0.05	0.48%		
Encroachments	0.04		0.04	0.38%	0.01	0.08
Animal Control	0.01		0.01	0.10%		
Erosion / Bank Caving	0.37		0.37	3.52%		
Unit Totals:	2.06	0.01	2.10	19.98%	0.01	0.08

Unit No. 02 Yolo Bypass	Overall Unit Rating	Total Unit Miles				
RD1600			U	4.22		
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Vegetation	0.92		0.92	21.80%		
Animal Control	0.03		0.03	0.71%		
Erosion / Bank Caving	0.65		0.65	15.40%		
Unit Totals:	1.60	0.00	1.60	37.92%	0.00	0.00

RD1601	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 1601 Twitchell			A	2.47		
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Erosion / Bank Caving	0.05		0.05	2.02%		
LMA Totals:	0.05	0.00	0.05	2.02%	0.00	0.00

RD1660	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 1660 Tisdale			A	12.14		
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Encroachments	0.01		0.01	0.08%		
LMA Totals:	0.01	0.00	0.01	0.08%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

**Fall 2010 Levee Maintenance Deficiency Summary Report
Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey**

Sacramento River Basin (cont.)

Unit No. 01 Sacramento River	Overall Unit Rating	Total Unit Miles				
RD1660 Not Inspected; 2009 Data	A	3.00				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments	0.01		0.01	0.33%		
<i>Unit Totals:</i>	0.01	0.00	0.01	0.33%	0.00	0.00
Unit No. 02 Sutter Bypass	Overall Unit Rating	Total Unit Miles				
RD1660 Not Inspected; 2009 Data	A	9.14				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
RD2035 Not Inspected; 2009 Data	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 2035 Conaway	A	12.09				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					3.79	
<i>LMA Totals:</i>	0.00	0.00	0.00	0.00%	3.79	0.00
Unit No. 01 Cache Creek Settling Basin	Overall Unit Rating	Total Unit Miles				
RD2035 Not Inspected; 2009 Data	A	2.01				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
Unit No. 02 Yolo Bypass	Overall Unit Rating	Total Unit Miles				
RD2035 Not Inspected; 2009 Data	A	7.57				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					1.78	
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	1.78	0.00
Unit No. 03 Willow Slough Bypass	Overall Unit Rating	Total Unit Miles				
RD2035 Not Inspected; 2009 Data	A	2.51				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					2.01	
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	2.01	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

RD2060 Reclamation District No. 2060 Hastings	Overall LMA Rating	Total LMA Miles				
	A	15.67				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Vegetation	0.18		0.18	1.15%		
Erosion / Bank Caving	0.01		0.01	0.06%		
Supplemental						
USACE Erosion Survey	0.16		0.16	1.02%		
LMA Totals:	0.35	0.00	0.35	2.23%	0.00	0.00

Unit No. 01 Lindsey Slough	Overall Unit Rating	Total Unit Miles				
RD2060 Not Inspected; 2009 Data	A	6.94				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Vegetation	0.18		0.18	2.59%		
Erosion / Bank Caving	0.01		0.01	0.14%		
Unit Totals:	0.19	0.00	0.19	2.74%	0.00	0.00

Unit No. 02 Ulatis Creek	Overall Unit Rating	Total Unit Miles				
RD2060 Not Inspected; 2009 Data	A	3.70				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
No Items						
Unit Totals:	0.00	0.00	0.00	0.00%	0.00	0.00

Unit No. 03 Cache Slough	Overall Unit Rating	Total Unit Miles				
RD2060 Not Inspected; 2009 Data	A	5.03				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Supplemental						
USACE Erosion Survey	0.16		0.16	3.18%		
Unit Totals:	0.16	0.00	0.16	3.18%	0.00	0.00

RD2068 Reclamation District No. 2068 Yolano	Overall LMA Rating	Total LMA Miles				
	A	8.73				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
No Items						
LMA Totals:	0.00	0.00	0.00	0.00%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 01 Yolo Bypass		Overall Unit Rating	Total Unit Miles				
RD2068	Not Inspected; 2009 Data	A	5.50				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
No Items							
Unit Totals:		0.00	0.00	0.00	0.00%	0.00	0.00

Unit No. 02 Back Levee		Overall Unit Rating	Total Unit Miles				
RD2068	Not Inspected; 2009 Data	A	3.23				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
No Items							
Unit Totals:		0.00	0.00	0.00	0.00%	0.00	0.00

RD2098		Overall LMA Rating	Total LMA Miles				
Reclamation District No. 2098 Cache and Haas Slough		A	10.96				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		1.06		1.06	9.67%		
LMA Totals:		1.06	0.00	1.06	9.67%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 01 Yolo Bypass	Overall Unit Rating	Total Unit Miles				
RD2098 Not Inspected; 2009 Data	U	3.58				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.92		0.92	25.70%		
<i>Unit Totals:</i>	0.92	0.00	0.92	25.70%	0.00	0.00
Unit No. 01A Cross Levee	Overall Unit Rating	Total Unit Miles				
RD2098 Not Inspected; 2009 Data	A	0.55				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
Unit No. 02 Cache Slough	Overall Unit Rating	Total Unit Miles				
RD2098 Not Inspected; 2009 Data	A	2.01				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
Unit No. 03 Haas Slough	Overall Unit Rating	Total Unit Miles				
RD2098 Not Inspected; 2009 Data	A	1.89				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
Unit No. 04 Back Levee	Overall Unit Rating	Total Unit Miles				
RD2098 Not Inspected; 2009 Data	A	2.93				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.14		0.14	4.78%		
<i>Unit Totals:</i>	0.14	0.00	0.14	4.78%	0.00	0.00
RD2103	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 2103						
Wheatland Vicinity	A	9.77				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Animal Control	0.01		0.01	0.10%		
<i>LMA Totals:</i>	0.01	0.00	0.01	0.10%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 01 South Dry Creek	Overall Unit Rating	Total Unit Miles				
RD2103 Not Inspected; 2009 Data	A	4.77				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
No Items					PO Miles	CO Miles
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

Unit No. 02 Bear River	Overall Unit Rating	Total Unit Miles				
RD2103 Not Inspected; 2009 Data	A	5.00				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
No Items					PO Miles	CO Miles
<i>Unit Totals:</i>	0.01	0.00	0.01	0.20%	0.00	0.00

RD2104	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 2104 Peters Pocket Tract	U	7.40				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
No Items					PO Miles	CO Miles
<i>LMA Totals:</i>	1.84	1.65	8.44	114.05%	0.00	0.00

ST0001	Overall LMA Rating	Total LMA Miles	* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.			
Sacramento Maintenance Yard Cache Creek	M *	25.52				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
No Items					PO Miles	CO Miles
<i>LMA Totals:</i>	0.52	0.18	1.24	4.86% *	1.19	0.12

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 01 North Levee		Overall Unit Rating	Total Unit Miles	* Overall Unit Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall Unit Rating is M instead of A.			
ST0001		M *	11.81				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
Earthen Levee							
Encroachments		0.23		0.23	1.95%	0.97	0.12
Supplemental							
USACE Erosion Survey		0.22	0.18	0.94	7.96%		
Unit Totals:		0.45	0.18	1.17	9.91% *	0.97	0.12

Unit No. 02 South Levee		Overall Unit Rating	Total Unit Miles				
ST0001		A	11.43				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
Earthen Levee							
Vegetation		0.02		0.02	0.18%		
Encroachments		0.05		0.05	0.44%	0.22	
Unit Totals:		0.07	0.00	0.07	0.61%	0.22	0.00

Unit No. 04 East Training Levee of Cache Creek Settling Basin		Overall Unit Rating	Total Unit Miles				
ST0001		A	2.28				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
No Items							
Unit Totals:		0.00	0.00	0.00	0.00%	0.00	0.00

ST0002		Overall LMA Rating	Total LMA Miles				
Sutter Maintenance Yard East Levee Sutter Bypass		A	22.12				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
Earthen Levee							
Encroachments							0.01
Animal Control		0.03		0.03	0.14%		
LMA Totals:		0.03	0.00	0.03	0.14%	0.00	0.01

ST0003		Overall LMA Rating	Total LMA Miles				
Sutter Maintenance Yard East Levee Sacramento River		A	27.17				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
Earthen Levee							
Vegetation		0.02		0.02	0.07%		
Trim / Thin Trees		0.01		0.01	0.04%		
Encroachments		0.19		0.19	0.70%		0.06
Animal Control		0.86		0.86	3.17%		
LMA Totals:		1.08	0.00	1.08	3.98%	0.00	0.06

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 01 Sacramento River	Overall Unit Rating	Total Unit Miles				
ST0003 Not Inspected; 2009 Data	A	20.39				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Trim / Thin Trees	0.01		0.01	0.05%		
Encroachments	0.19		0.19	0.93%		0.06
Animal Control	0.82		0.82	4.02%		
<i>Unit Totals:</i>	1.02	0.00	1.02	5.00%	0.00	0.06
Unit No. 02 Colusa Bypass	Overall Unit Rating	Total Unit Miles				
ST0003 Not Inspected; 2009 Data	A	2.20				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
Unit No. 03 Colusa Bypass	Overall Unit Rating	Total Unit Miles				
ST0003 Not Inspected; 2009 Data	A	2.28				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.02		0.02	0.88%		
<i>Unit Totals:</i>	0.02	0.00	0.02	0.88%	0.00	0.00
Unit No. 04 Moulton Bypass	Overall Unit Rating	Total Unit Miles				
ST0003 Not Inspected; 2009 Data	A	0.30				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Animal Control	0.01		0.01	3.33%		
<i>Unit Totals:</i>	0.01	0.00	0.01	3.33%	0.00	0.00
Unit No. 05 Moulton Bypass	Overall Unit Rating	Total Unit Miles				
ST0003 Not Inspected; 2009 Data	A	2.00				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Animal Control	0.03		0.03	1.50%		
<i>Unit Totals:</i>	0.03	0.00	0.03	1.50%	0.00	0.00
ST0004	Overall LMA Rating	Total LMA Miles				
Not Inspected; 2009 Data	A	2.00				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>LMA Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

ST0005	Overall LMA Rating	Total LMA Miles				
Sutter Maintenance Yard Hamilton Bend	A	3.22				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
No Items					PO Miles	CO Miles
<i>LMA Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

ST0006	Overall LMA Rating	Total LMA Miles				
Sutter Maintenance Yard Nelson Bend	U	0.50				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.99		0.99	198.00%		
Trim / Thin Trees	0.44		0.44	88.00%		
Encroachments						0.01
<i>LMA Totals:</i>	1.43	0.00	1.43	286.00%	0.00	0.01

ST0007	Overall LMA Rating	Total LMA Miles				
Sacramento Maintenance Yard Putah Creek	A	16.29				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Trim / Thin Trees	0.11		0.11	0.68%		
Encroachments	0.01		0.01	0.06%	3.08	
Animal Control	0.06		0.06	0.37%		
Erosion / Bank Caving	0.02		0.02	0.12%		
<i>LMA Totals:</i>	0.20	0.00	0.20	1.23%	3.08	0.00

Unit No. 01 Putah Creek or North Levee	Overall Unit Rating	Total Unit Miles				
ST0007	A	8.99				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments	0.01		0.01	0.11%	2.44	
<i>Unit Totals:</i>	0.01	0.00	0.01	0.11%	2.44	0.00

Unit No. 02 Putah Creek or South Levee	Overall Unit Rating	Total Unit Miles				
ST0007	A	7.30				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Trim / Thin Trees	0.11		0.11	1.51%		
Encroachments					0.64	
Animal Control	0.06		0.06	0.82%		
Erosion / Bank Caving	0.02		0.02	0.27%		
<i>Unit Totals:</i>	0.19	0.00	0.19	2.60%	0.64	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

ST0008		Overall LMA Rating	Total LMA Miles				
Sacramento Maintenance Yard Sacramento Bypass		A	3.51				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles		
Earthen Levee							
Encroachments	0.01		0.01	0.29%			
LMA Totals:	0.01	0.00	0.01	0.29%	0.00	0.00	
Unit No. 01 Sacramento Bypass or North Levee	Overall Unit Rating	Total Unit Miles					
ST0008	A	1.73					
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles		
No Items							
Unit Totals:	0.00	0.00	0.00	0.00%	0.00	0.00	
Unit No. 02 Sacramento Bypass or South Levee	Overall Unit Rating	Total Unit Miles					
ST0008	A	1.78					
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles		
Earthen Levee							
Encroachments	0.01		0.01	0.56%			
Unit Totals:	0.01	0.00	0.01	0.56%	0.00	0.00	
ST0009	Not Inspected; 2009 Data	Overall LMA Rating	Total LMA Miles				
Sutter Maintenance Yard Tisdale Bypass		A	8.93				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles		
No Items							
LMA Totals:	0.00	0.00	0.00	0.00%	0.00	0.00	
Unit No. 01 Tisdale Bypass	Overall Unit Rating	Total Unit Miles					
ST0009	Not Inspected; 2009 Data	A	4.50				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles		
No Items							
Unit Totals:	0.00	0.00	0.00	0.00%	0.00	0.00	
Unit No. 02 Tisdale Bypass	Overall Unit Rating	Total Unit Miles					
ST0009	Not Inspected; 2009 Data	A	4.43				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles		
No Items							
Unit Totals:	0.00	0.00	0.00	0.00%	0.00	0.00	

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

ST0010	Overall LMA Rating	Total LMA Miles				
Sutter Maintenance Yard Wadsworth Canal						
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Animal Control	0.04		0.04	0.43%		
Erosion / Bank Caving	0.54		0.54	5.79%		
LMA Totals:	0.58	0.00	0.58	6.22%	0.00	0.00
Unit No. 01 Wadsworth Canal	Overall Unit Rating	Total Unit Miles				
ST0010	A	4.66				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Erosion / Bank Caving	0.12		0.12	2.58%		
Unit Totals:	0.12	0.00	0.12	2.58%	0.00	0.00
Unit No. 02 Wadsworth Canal	Overall Unit Rating	Total Unit Miles				
ST0010	A	4.66				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Animal Control	0.04		0.04	0.86%		
Erosion / Bank Caving	0.42		0.42	9.01%		
Unit Totals:	0.46	0.00	0.46	9.87%	0.00	0.00
ST0011	Overall LMA Rating	Total LMA Miles	* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.			
Sacramento Maintenance Yard West Levee Yolo Bypass						
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Encroachments		0.01	0.04	0.43%	3.52	
Cracking	0.07		0.07	0.75%		
Supplemental						
USACE Erosion Survey	0.15		0.15	1.61%		
LMA Totals:	0.22	0.01	0.26	2.79% *	3.52	0.00

**Flood Control Project Maintenance
Levee Inspections**

**Fall 2010 Levee Maintenance Deficiency Summary Report
Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey**

Sacramento River Basin (cont.)

Unit No. 01 West Levee	Overall Unit Rating	Total Unit Miles				
ST0011	A	2.72				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					0.84	
<i>Supplemental</i>						
USACE Erosion Survey	0.15		0.15	5.52%		
<i>Unit Totals:</i>	0.15	0.00	0.15	5.52%	0.84	0.00
Unit No. 02 West Levee	Overall Unit Rating	Total Unit Miles				
ST0011	A	1.52				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					0.92	
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.92	0.00
Unit No. 03 West Levee	Overall Unit Rating	Total Unit Miles				
ST0011	A	1.48				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
Unit No. 04 West Levee	Overall Unit Rating	Total Unit Miles	* Overall Unit Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall Unit Rating is M instead of A.			
ST0011	M *	3.61				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments		0.01	0.04	1.11%	1.76	
Cracking	0.07		0.07	1.94%		
<i>Unit Totals:</i>	0.07	0.01	0.11	3.05% *	1.76	0.00
ST0012 Not Inspected; 2009 Data	Overall LMA Rating	Total LMA Miles				
Sacramento Maintenance Yard Willow Slough Bypass	A	12.46				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					0.49	
<i>Supplemental</i>						
USACE Erosion Survey	0.54		0.54	4.33%		
<i>LMA Totals:</i>	0.54	0.00	0.54	4.33%	0.49	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 01 Willow Slough Bypass or North Levee	Overall Unit Rating	Total Unit Miles				
ST0012 Not Inspected; 2009 Data	A	5.09				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					0.47	
<i>Supplemental</i>						
USACE Erosion Survey	0.40		0.40	7.86%		
<i>Unit Totals:</i>	0.40	0.00	0.40	7.86%	0.47	0.00

Unit No. 02 Willow Slough Bypass or South Levee	Overall Unit Rating	Total Unit Miles				
ST0012 Not Inspected; 2009 Data	A	7.37				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					0.02	
<i>Supplemental</i>						
USACE Erosion Survey	0.14		0.14	1.90%		
<i>Unit Totals:</i>	0.14	0.00	0.14	1.90%	0.02	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin

NA0010	Overall LMA Rating	Total LMA Miles	* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.			
Lower San Joaquin Levee District						
	M *	197.28				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	0.21		0.21	0.11%		
Trim / Thin Trees	0.01		0.01	0.01%		
Encroachments		0.01	0.04	0.02%	0.55	0.01
Animal Control	0.88		0.88	0.45%		
Slope Stability	0.02		0.02	0.01%		
Erosion / Bank Caving	0.01		0.01	0.01%		
Repair Gates	0.01		0.01	0.01%		
Channels						
Encroachments	0.02		0.02	0.01%		
LMA Totals:	1.16	0.01	1.20	0.61% *	0.55	0.01

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

Unit No. 01 San Joaquin River	Overall Unit Rating	Total Unit Miles				
NA0010	A	22.56				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					0.55	
Animal Control	0.06		0.06	0.27%		
<i>Unit Totals:</i>	0.06	0.00	0.06	0.27%	0.55	0.00
Unit No. 02A San Joaquin River	Overall Unit Rating	Total Unit Miles				
NA0010	A	13.79				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments						0.01
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.01
Unit No. 02B San Joaquin River	Overall Unit Rating	Total Unit Miles				
NA0010	A	5.92				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Animal Control	0.01		0.01	0.17%		
<i>Unit Totals:</i>	0.01	0.00	0.01	0.17%	0.00	0.00
Unit No. 03 San Joaquin River	Overall Unit Rating	Total Unit Miles				
NA0010	A	2.16				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
Unit No. 04 San Joaquin River	Overall Unit Rating	Total Unit Miles				
NA0010	A	1.58				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
Unit No. 05 East Side Bypass	Overall Unit Rating	Total Unit Miles				
NA0010	A	34.75				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Trim / Thin Trees	0.01		0.01	0.03%		
Animal Control	0.09		0.09	0.26%		
Repair Gates	0.01		0.01	0.03%		
<i>Unit Totals:</i>	0.11	0.00	0.11	0.32%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

Unit No. 06 East Side Bypass	Overall Unit Rating	Total Unit Miles				
NA0010	A	36.38				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Animal Control	0.09		0.09	0.25%		
<i>Unit Totals:</i>	0.09	0.00	0.09	0.25%	0.00	0.00
Unit No. 07 Bear Creek Bypass	Overall Unit Rating	Total Unit Miles				
NA0010	A	3.62				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
Unit No. 08 Bear Creek Bypass	Overall Unit Rating	Total Unit Miles				
NA0010	A	3.63				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Animal Control	0.17		0.17	4.68%		
<i>Unit Totals:</i>	0.17	0.00	0.17	4.68%	0.00	0.00
Unit No. 09 Owens Creek Bypass	Overall Unit Rating	Total Unit Miles				
NA0010	A	0.88				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
Unit No. 10 Owens Creek Bypass	Overall Unit Rating	Total Unit Miles				
NA0010	A	0.82				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
Unit No. 11 Mariposa Bypass	Overall Unit Rating	Total Unit Miles				
NA0010	A	3.31				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
Unit No. 12 Mariposa Bypass	Overall Unit Rating	Total Unit Miles				
NA0010	A	3.33				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Animal Control	0.02		0.02	0.60%		
<i>Unit Totals:</i>	0.02	0.00	0.02	0.60%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

Unit No. 13 Ash Slough	Overall Unit Rating	Total Unit Miles				
NA0010	A	1.28				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Animal Control	0.01		0.01	0.78%		
<i>Unit Totals:</i>	0.01	0.00	0.01	0.78%	0.00	0.00
Unit No. 14 Ash Slough	Overall Unit Rating	Total Unit Miles				
NA0010	A	1.28				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
Unit No. 15 Berenda Slough	Overall Unit Rating	Total Unit Miles				
NA0010	A	2.03				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
Unit No. 16 Berenda Slough	Overall Unit Rating	Total Unit Miles				
NA0010	A	1.98				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
Unit No. 17 Chowchilla Canal Bypass	Overall Unit Rating	Total Unit Miles				
NA0010	A	16.09				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Animal Control	0.38		0.38	2.36%		
<i>Unit Totals:</i>	0.38	0.00	0.38	2.36%	0.00	0.00
Unit No. 18 Chowchilla Canal Bypass	Overall Unit Rating	Total Unit Miles				
NA0010	A	15.33				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

**Fall 2010 Levee Maintenance Deficiency Summary Report
Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey**

San Joaquin River Basin (cont.)

Unit No. 22A East Side Canal	Overall Unit Rating	Total Unit Miles				
NA0010	A	5.50				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.20		0.20	3.64%		
Slope Stability	0.02		0.02	0.36%		
Erosion / Bank Caving	0.01		0.01	0.18%		
<i>Channels</i>						
Encroachments	0.02		0.02	0.36%		
<i>Unit Totals:</i>	0.25	0.00	0.25	4.55%	0.00	0.00
Unit No. 23 San Joaquin River	Overall Unit Rating	Total Unit Miles	* Overall Unit Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall Unit Rating is M instead of A.			
NA0010	M *	10.25				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.01		0.01	0.10%		
Encroachments		0.01	0.04	0.39%		
Animal Control	0.04		0.04	0.39%		
<i>Unit Totals:</i>	0.05	0.01	0.09	0.88% *	0.00	0.00
Unit No. 24 San Joaquin River	Overall Unit Rating	Total Unit Miles				
NA0010	A	8.34				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Animal Control	0.01		0.01	0.12%		
<i>Unit Totals:</i>	0.01	0.00	0.01	0.12%	0.00	0.00
Unit No. 25 Salt Slough	Overall Unit Rating	Total Unit Miles				
NA0010	A	2.47				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
NA0011	Overall LMA Rating	Total LMA Miles				
Madera County FCWCA	U	26.65				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.14		0.14	0.53%		
Trim / Thin Trees	0.34		0.34	1.28%		
Encroachments	0.16	0.01	0.20	0.75%	0.09	
Animal Control	8.31		8.31	31.18%		
<i>Supplemental</i>						
DWR Erosion Survey	0.12		0.12	0.45%		
<i>LMA Totals:</i>	9.07	0.01	9.11	34.18%	0.09	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

Unit No. 01 Ash Slough	Overall Unit Rating	Total Unit Miles				
NA0011	M	2.41				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.02		0.02	0.83%		
Encroachments	0.07	0.01	0.11	4.56%		
Animal Control	0.04		0.04	1.66%		
<i>Supplemental</i>						
DWR Erosion Survey	0.12		0.12	4.98%		
<i>Unit Totals:</i>	0.25	0.01	0.29	12.03%	0.00	0.00

Unit No. 02 Ash Slough	Overall Unit Rating	Total Unit Miles				
NA0011	M	2.07				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.02		0.02	0.97%		
Trim / Thin Trees	0.28		0.28	13.53%		
Encroachments	0.05		0.05	2.42%	0.09	
<i>Unit Totals:</i>	0.35	0.00	0.35	16.91%	0.09	0.00

Unit No. 03 Berenda Slough	Overall Unit Rating	Total Unit Miles				
NA0011	U	1.55				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.06		0.06	3.87%		
Trim / Thin Trees	0.06		0.06	3.87%		
Encroachments	0.01		0.01	0.65%		
Animal Control	0.22		0.22	14.19%		
<i>Unit Totals:</i>	0.35	0.00	0.35	22.58%	0.00	0.00

Unit No. 04 Berenda Slough	Overall Unit Rating	Total Unit Miles				
NA0011	U	2.28				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.02		0.02	0.88%		
Encroachments	0.01		0.01	0.44%		
Animal Control	0.93		0.93	40.79%		
<i>Unit Totals:</i>	0.96	0.00	0.96	42.11%	0.00	0.00

Unit No. 05 Fresno River	Overall Unit Rating	Total Unit Miles				
NA0011	U	9.20				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.01		0.01	0.11%		
Encroachments	0.01		0.01	0.11%		
Animal Control	6.30		6.30	68.48%		
<i>Unit Totals:</i>	6.32	0.00	6.32	68.70%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

Unit No. 06 Fresno River	Overall Unit Rating	Total Unit Miles				
NA0011	A	9.14				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.01		0.01	0.11%		
Encroachments	0.01		0.01	0.11%		
Animal Control	0.82		0.82	8.97%		
<i>Unit Totals:</i>	0.84	0.00	0.84	9.19%	0.00	0.00
NA0013	Overall LMA Rating	Total LMA Miles				
Merced Streams Group	U	6.40				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.01	0.32	1.29	20.16%		
Trim / Thin Trees	0.04		0.04	0.63%		
Encroachments	0.07		0.07	1.09%	0.01	
Animal Control	0.61	0.04	0.77	12.03%		
<i>Interior Drainage & Piping Systems</i>						
Culverts: Inlets / Outlets	0.01		0.01	0.16%		
<i>Channels</i>						
Vegetation & Obstructions		0.01	0.04	0.63%		
Encroachments	1.14		1.14	17.81%		
<i>Supplemental</i>						
DWR Erosion Survey	0.15	0.01	0.19	2.97%		
<i>LMA Totals:</i>	2.03	0.38	3.55	55.47%	0.01	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

Unit No. 01 Black Rascal Diversion	Overall Unit Rating	Total Unit Miles				
NA0013	U	1.64				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation		0.32	1.28	78.05%		
<i>Unit Totals:</i>	0.00	0.32	1.28	78.05%	0.00	0.00
Unit No. 02 Black Rascal Diversion	Overall Unit Rating	Total Unit Miles				
NA0013	U	1.88				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments	0.01		0.01	0.53%	0.01	
Animal Control	0.31		0.31	16.49%		
<i>Channels</i>						
Encroachments	1.14		1.14	60.64%		
<i>Unit Totals:</i>	1.46	0.00	1.46	77.66%	0.01	0.00
Unit No. 03 Owens Creek Diversion	Overall Unit Rating	Total Unit Miles				
NA0013	M	1.44				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.01		0.01	0.69%		
Trim / Thin Trees	0.03		0.03	2.08%		
Animal Control	0.09		0.09	6.25%		
<i>Channels</i>						
Vegetation & Obstructions		0.01	0.04	2.78%		
<i>Supplemental</i>						
DWR Erosion Survey	0.01	0.01	0.05	3.47%		
<i>Unit Totals:</i>	0.14	0.02	0.22	15.28%	0.00	0.00
Unit No. 04 Owens Creek Diversion	Overall Unit Rating	Total Unit Miles				
NA0013	U	1.44				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Trim / Thin Trees	0.01		0.01	0.69%		
Encroachments	0.06		0.06	4.17%		
Animal Control	0.21	0.04	0.37	25.69%		
<i>Interior Drainage & Piping Systems</i>						
Culverts: Inlets / Outlets	0.01		0.01	0.69%		
<i>Supplemental</i>						
DWR Erosion Survey	0.14		0.14	9.72%		
<i>Unit Totals:</i>	0.43	0.04	0.59	40.97%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

NA0017	Overall LMA Rating	Total LMA Miles				
San Joaquin County Flood Control and Water Conservation District						
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	10.79		10.79	10.38%		
Trim / Thin Trees	0.49		0.49	0.47%		
Encroachments	6.29	1.10	10.69	10.28%	18.43	1.46
Animal Control	0.77	0.04	0.93	0.89%		
Slope Stability	0.25	0.02	0.33	0.32%		
Erosion / Bank Caving	0.50	0.01	0.54	0.52%		
Crown Surface / Depressions / Rutting	0.09		0.09	0.09%		
Interior Drainage & Piping Systems						
Culverts: Inlets / Outlets	0.01		0.01	0.01%		
Flap Gates	0.01	0.03	0.13	0.13%		
Sluice / Slide Gates		0.01	0.04	0.04%		
Concrete Floodwalls						
Monolith Joints	0.01		0.01	0.01%		
Supplemental						
DWR Erosion Survey	0.02	0.99	3.98	3.83%		
LMA Totals:	19.23	2.20	28.03	26.96%	18.43	1.46

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

Unit No. 01 Littlejohn Creek		Overall Unit Rating	Total Unit Miles				
NA0017		U	2.87				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		2.04		2.04	71.08%		
Trim / Thin Trees		0.01		0.01	0.35%		
Encroachments		3.61	0.71	6.45	224.74%		
<i>Interior Drainage & Piping Systems</i>							
Flap Gates		0.01	0.01	0.05	1.74%		
Sluice / Slide Gates			0.01	0.04	1.39%		
<i>Unit Totals:</i>		5.67	0.73	8.59	299.30%	0.00	0.00

Unit No. 02 Littlejohn Creek		Overall Unit Rating	Total Unit Miles				
NA0017		U	3.21				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		4.63		4.63	144.24%		
Encroachments		0.17		0.17	5.30%	0.51	
<i>Unit Totals:</i>		4.80	0.00	4.80	149.53%	0.51	0.00

Unit No. 06 SPRR Drain		Overall Unit Rating	Total Unit Miles				
NA0017		A	0.50				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Erosion / Bank Caving		0.01		0.01	2.00%		
<i>Unit Totals:</i>		0.01	0.00	0.01	2.00%	0.00	0.00

Unit No. 07 Bear Creek		Overall Unit Rating	Total Unit Miles	* Overall Unit Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall Unit Rating is M instead of A.			
NA0017		M *	16.69				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		0.20		0.20	1.20%		
Trim / Thin Trees		0.04		0.04	0.24%		
Encroachments		0.61		0.61	3.66%	1.23	0.01
Animal Control		0.07	0.02	0.15	0.90%		
Slope Stability		0.01		0.01	0.06%		
Erosion / Bank Caving		0.04		0.04	0.24%		
Crown Surface / Depressions / Rutting		0.02		0.02	0.12%		
<i>Unit Totals:</i>		0.99	0.02	1.07	6.41% *	1.23	0.01

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

Unit No. 08 Bear Creek	Overall Unit Rating	Total Unit Miles				
NA0017	A	16.47				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.15		0.15	0.91%		
Trim / Thin Trees	0.11		0.11	0.67%		
Encroachments	0.13		0.13	0.79%	1.64	0.60
Animal Control	0.23		0.23	1.40%		
Slope Stability	0.06		0.06	0.36%		
Erosion / Bank Caving	0.04		0.04	0.24%		
Crown Surface / Depressions / Rutting	0.03		0.03	0.18%		
<i>Unit Totals:</i>	0.75	0.00	0.75	4.55%	1.64	0.60
Unit No. 09 Paddy Creek	Overall Unit Rating	Total Unit Miles				
NA0017	A	1.54				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Trim / Thin Trees	0.01		0.01	0.65%		
Encroachments					0.54	
<i>Unit Totals:</i>	0.01	0.00	0.01	0.65%	0.54	0.00
Unit No. 10 Paddy Creek	Overall Unit Rating	Total Unit Miles				
NA0017	A	1.42				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Trim / Thin Trees	0.02		0.02	1.41%		
Encroachments	0.01		0.01	0.70%	1.23	
Animal Control	0.02		0.02	1.41%		
<i>Interior Drainage & Piping Systems</i>						
Culverts: Inlets / Outlets	0.01		0.01	0.70%		
<i>Unit Totals:</i>	0.06	0.00	0.06	4.23%	1.23	0.00
Unit No. 11 North Paddy Creek	Overall Unit Rating	Total Unit Miles				
NA0017	M	3.56				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.02		0.02	0.56%		
Encroachments	0.25		0.25	7.02%	1.01	
Animal Control	0.06		0.06	1.69%		
Slope Stability	0.10		0.10	2.81%		
Crown Surface / Depressions / Rutting	0.01		0.01	0.28%		
<i>Unit Totals:</i>	0.44	0.00	0.44	12.36%	1.01	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

Unit No. 12 North Paddy Creek	Overall Unit Rating	Total Unit Miles				
NA0017	U	3.53				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.01		0.01	0.28%		
Trim / Thin Trees	0.01		0.01	0.28%		
Encroachments	0.01	0.39	1.57	44.48%	1.33	
<i>Interior Drainage & Piping Systems</i>						
Flap Gates		0.01	0.04	1.13%		
<i>Unit Totals:</i>	0.03	0.40	1.63	46.18%	1.33	0.00
Unit No. 13 Middle Paddy Creek	Overall Unit Rating	Total Unit Miles				
NA0017	M	1.40				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.12		0.12	8.57%		
Encroachments	0.01		0.01	0.71%	1.39	
Animal Control	0.05	0.01	0.09	6.43%		
Erosion / Bank Caving	0.01		0.01	0.71%		
<i>Interior Drainage & Piping Systems</i>						
Flap Gates		0.01	0.04	2.86%		
<i>Unit Totals:</i>	0.19	0.02	0.27	19.29%	1.39	0.00
Unit No. 14 Middle Paddy Creek	Overall Unit Rating	Total Unit Miles				
NA0017	A	1.40				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Animal Control	0.02		0.02	1.43%		
<i>Unit Totals:</i>	0.02	0.00	0.02	1.43%	0.00	0.00
Unit No. 15 Mormon Slough	Overall Unit Rating	Total Unit Miles				
NA0017	U	25.62				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	3.36		3.36	13.12%		
Trim / Thin Trees	0.17		0.17	0.66%		
Encroachments	0.72		0.72	2.81%	5.61	0.34
Animal Control	0.19	0.01	0.23	0.90%		
Slope Stability	0.04	0.01	0.08	0.31%		
Erosion / Bank Caving	0.40	0.01	0.44	1.72%		
<i>Concrete Floodwalls</i>						
Monolith Joints	0.01		0.01	0.04%		
<i>Supplemental</i>						
DWR Erosion Survey	0.01	0.99	3.97	15.50%		
<i>Unit Totals:</i>	4.90	1.02	8.98	35.05%	5.61	0.34

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

Unit No. 16 Mormon Slough	Overall Unit Rating	Total Unit Miles	* Overall Unit Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall Unit Rating is M instead of A.			
NA0017	M *	24.00				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.26		0.26	1.08%		
Trim / Thin Trees	0.12		0.12	0.50%		
Encroachments	0.71		0.71	2.96%	3.94	0.51
Animal Control	0.13		0.13	0.54%		
Slope Stability	0.04	0.01	0.08	0.33%		
Crown Surface / Depressions / Rutting	0.03		0.03	0.13%		
<i>Supplemental</i>						
DWR Erosion Survey	0.01		0.01	0.04%		
<i>Unit Totals:</i>	1.30	0.01	1.34	5.58% *	3.94	0.51

Unit No. 17 Potter Creek	Overall Unit Rating	Total Unit Miles				
NA0017	A	0.86				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments	0.06		0.06	6.98%		
<i>Unit Totals:</i>	0.06	0.00	0.06	6.98%	0.00	0.00

Unit No. 18 Potter Creek	Overall Unit Rating	Total Unit Miles				
NA0017	A	0.89				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

RD0001	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0001 Union Island	U	1.15				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.38		0.38	33.04%		
Encroachments	0.01		0.01	0.87%		
Animal Control	0.01		0.01	0.87%		
Erosion / Bank Caving	0.02	0.01	0.06	5.22%		
<i>LMA Totals:</i>	0.42	0.01	0.46	40.00%	0.00	0.00

RD0017	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0017 Mossdale	A	16.24				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.03		0.03	0.19%		
Encroachments					0.30	
<i>LMA Totals:</i>	0.03	0.00	0.03	0.19%	0.30	0.00

**Flood Control Project Maintenance
Levee Inspections**

**Fall 2010 Levee Maintenance Deficiency Summary Report
Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey**

San Joaquin River Basin (cont.)

Unit No. 01 French Camp Slough	Overall Unit Rating	Total Unit Miles				
RD0017	A	1.79				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
No Items					PO Miles	CO Miles
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

Unit No. 02 San Joaquin River	Overall Unit Rating	Total Unit Miles				
RD0017	A	14.45				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.03		0.03	0.21%		
Encroachments					0.30	
<i>Unit Totals:</i>	0.03	0.00	0.03	0.21%	0.30	0.00

RD0404	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0404 Boggs	U	4.12				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.73		0.73	17.72%		
Encroachments	0.04		0.04	0.97%	0.05	
Animal Control	0.32		0.32	7.77%		
Slope Stability	0.02		0.02	0.49%		
Erosion / Bank Caving	0.03		0.03	0.73%		
Repair Gates		0.01	0.04	0.97%		
<i>Supplemental</i>						
DWR Erosion Survey		0.30	1.20	29.13%		
<i>LMA Totals:</i>	1.14	0.31	2.38	57.77%	0.05	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

Unit No. 01 San Joaquin River		Overall Unit Rating	Total Unit Miles				
RD0404		U	2.36				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		0.64		0.64	27.12%		
Animal Control		0.10		0.10	4.24%		
Slope Stability		0.02		0.02	0.85%		
Erosion / Bank Caving		0.03		0.03	1.27%		
Repair Gates			0.01	0.04	1.69%		
<i>Supplemental</i>							
DWR Erosion Survey			0.04	0.16	6.78%		
<i>Unit Totals:</i>		0.79	0.05	0.99	41.95%	0.00	0.00

Unit No. 02 French Camp Slough		Overall Unit Rating	Total Unit Miles				
RD0404		U	1.76				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		0.09		0.09	5.11%		
Encroachments		0.04		0.04	2.27%	0.05	
Animal Control		0.22		0.22	12.50%		
<i>Supplemental</i>							
DWR Erosion Survey			0.26	1.04	59.09%		
<i>Unit Totals:</i>		0.35	0.26	1.39	78.98%	0.05	0.00

RD0524		Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0524 Middle Roberts Island		U	6.26				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		0.22	0.10	0.62	9.90%		
Trim / Thin Trees		0.78	0.01	0.82	13.10%		
Encroachments		0.25	0.01	0.29	4.63%	0.09	0.24
Animal Control		0.35		0.35	5.59%		
Slope Stability		0.12		0.12	1.92%		
Erosion / Bank Caving		0.23	0.02	0.31	4.95%		
Crown Surface / Depressions / Rutting		0.02		0.02	0.32%		
<i>Supplemental</i>							
DWR Erosion Survey		0.02	0.22	0.90	14.38%		
<i>LMA Totals:</i>		1.99	0.36	3.43	54.79%	0.09	0.24

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

RD0544	Overall LMA Rating		Total LMA Miles			
Reclamation District No. 0544 Upper Roberts Island	U		10.33			
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Vegetation	9.52	0.39	11.08	107.26%		
Trim / Thin Trees	0.03		0.03	0.29%		
Encroachments	0.27		0.27	2.61%	0.11	0.01
Animal Control	0.23		0.23	2.23%		
Slope Stability	0.03	0.01	0.07	0.68%		
Erosion / Bank Caving	0.01		0.01	0.10%		
Crown Surface / Depressions / Rutting	0.34		0.34	3.29%		
Interior Drainage & Piping Systems						
Erosion Areas		0.01	0.04	0.39%		
Supplemental						
DWR Erosion Survey		0.04	0.16	1.55%		
LMA Totals:	10.43	0.45	12.23	118.39%	0.11	0.01

Unit No. 01 San Joaquin River	Overall Unit Rating	Total Unit Miles				
RD0544	U	6.11				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Vegetation	4.00	0.37	5.48	89.69%		
Trim / Thin Trees	0.02		0.02	0.33%		
Encroachments	0.21		0.21	3.44%	0.05	0.01
Animal Control	0.11		0.11	1.80%		
Slope Stability	0.03	0.01	0.07	1.15%		
Erosion / Bank Caving	0.01		0.01	0.16%		
Supplemental						
DWR Erosion Survey		0.04	0.16	2.62%		
Unit Totals:	4.38	0.42	6.06	99.18%	0.05	0.01

Unit No. 02 Old River	Overall Unit Rating	Total Unit Miles				
RD0544	U	4.22				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Vegetation	5.52	0.02	5.60	132.70%		
Trim / Thin Trees	0.01		0.01	0.24%		
Encroachments	0.06		0.06	1.42%	0.06	
Animal Control	0.12		0.12	2.84%		
Crown Surface / Depressions / Rutting	0.34		0.34	8.06%		
Interior Drainage & Piping Systems						
Erosion Areas		0.01	0.04	0.95%		
Unit Totals:	6.05	0.03	6.17	146.21%	0.06	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

RD1602	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 1602 Del Puerto	M	6.29				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.64		0.64	10.18%		
Trim / Thin Trees	0.04		0.04	0.64%		
Encroachments	0.01		0.01	0.16%	1.75	
Animal Control	0.31		0.31	4.93%		
Slope Stability	0.04		0.04	0.64%		
<i>Interior Drainage & Piping Systems</i>						
Encroachments	0.01		0.01	0.16%		
Flap Gates	0.01		0.01	0.16%		
Concrete Tilting / Settlement	0.01		0.01	0.16%		
<i>LMA Totals:</i>	1.07	0.00	1.07	17.01%	1.75	0.00
RD2031	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 2031 Elliot	A	13.19				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.10		0.10	0.76%		
Trim / Thin Trees	0.61		0.61	4.63%		
Encroachments	0.02		0.02	0.15%	0.77	0.13
Crown Surface / Depressions / Rutting	0.03		0.03	0.23%		
<i>Supplemental</i>						
DWR Erosion Survey	0.04		0.04	0.30%		
<i>LMA Totals:</i>	0.80	0.00	0.80	6.07%	0.77	0.13
Unit No. 01 Stanislaus River	Overall Unit Rating	Total Unit Miles				
RD2031	A	7.15				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.09		0.09	1.26%		
Trim / Thin Trees	0.01		0.01	0.14%		
Encroachments	0.02		0.02	0.28%	0.77	0.11
Crown Surface / Depressions / Rutting	0.03		0.03	0.42%		
<i>Supplemental</i>						
DWR Erosion Survey	0.04		0.04	0.56%		
<i>Unit Totals:</i>	0.19	0.00	0.19	2.66%	0.77	0.11
Unit No. 02 San Joaquin River	Overall Unit Rating	Total Unit Miles				
RD2031	M	6.04				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.01		0.01	0.17%		
Trim / Thin Trees	0.60		0.60	9.93%		
Encroachments						0.02
<i>Unit Totals:</i>	0.61	0.00	0.61	10.10%	0.00	0.02

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

RD2058	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 2058 Pescadero	U	6.71				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	9.83	0.02	9.91	147.69%		
Trim / Thin Trees	0.28	0.14	0.84	12.52%		
Encroachments	0.02		0.02	0.30%	0.06	
Animal Control	0.07		0.07	1.04%		
<i>Supplemental</i>						
DWR Erosion Survey	0.05		0.05	0.75%		
<i>LMA Totals:</i>	10.25	0.16	10.89	162.30%	0.06	0.00

RD2062	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 2062 Stewart	U	12.35				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.47		0.47	3.81%		
Trim / Thin Trees	0.02		0.02	0.16%		
Encroachments	1.43		1.43	11.58%		
Animal Control	0.10	0.01	0.14	1.13%		
Erosion / Bank Caving	0.02		0.02	0.16%		
Crown Surface / Depressions / Rutting	0.01		0.01	0.08%		
<i>Supplemental</i>						
DWR Erosion Survey	0.14	0.11	0.58	4.70%		
<i>LMA Totals:</i>	2.19	0.12	2.67	21.62%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

Unit No. 01 San Joaquin River	Overall Unit Rating	Total Unit Miles				
RD2062	M	2.69				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.47		0.47	17.47%		
Crown Surface / Depressions / Rutting	0.01		0.01	0.37%		
<i>Supplemental</i>						
DWR Erosion Survey	0.01		0.01	0.37%		
<i>Unit Totals:</i>	0.49	0.00	0.49	18.22%	0.00	0.00
Unit No. 02 Paradise Cut	Overall Unit Rating	Total Unit Miles				
RD2062	U	4.03				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments	1.40		1.40	34.74%		
<i>Supplemental</i>						
DWR Erosion Survey	0.11		0.11	2.73%		
<i>Unit Totals:</i>	1.51	0.00	1.51	37.47%	0.00	0.00
Unit No. 03 Old River	Overall Unit Rating	Total Unit Miles				
RD2062	M	5.63				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Trim / Thin Trees	0.02		0.02	0.36%		
Encroachments	0.03		0.03	0.53%		
Animal Control	0.10	0.01	0.14	2.49%		
Erosion / Bank Caving	0.02		0.02	0.36%		
<i>Supplemental</i>						
DWR Erosion Survey	0.02	0.11	0.46	8.17%		
<i>Unit Totals:</i>	0.19	0.12	0.67	11.90%	0.00	0.00
RD2063	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 2063 Crows Landing	U	10.63				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	2.34		2.34	22.01%		
Trim / Thin Trees	0.01		0.01	0.09%		
Encroachments	0.01	0.01	0.05	0.47%	0.01	
Animal Control	0.10		0.10	0.94%		
Slope Stability	0.01		0.01	0.09%		
Erosion / Bank Caving		0.16	0.64	6.02%		
Crown Surface / Depressions / Rutting	0.24		0.24	2.26%		
<i>Channels</i>						
Encroachments		0.01	0.04	0.38%		
<i>LMA Totals:</i>	2.71	0.18	3.43	32.27%	0.01	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

RD2064	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 2064 River Junction	A	11.90				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Vegetation	0.01		0.01	0.08%		
LMA Totals:	0.01	0.00	0.01	0.08%	0.00	0.00
Unit No. 01 San Joaquin River	Overall Unit Rating	Total Unit Miles				
RD2064	A	5.70				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Vegetation	0.01		0.01	0.18%		
Unit Totals:	0.01	0.00	0.01	0.18%	0.00	0.00
Unit No. 02 Stanislaus River	Overall Unit Rating	Total Unit Miles				
RD2064	A	6.20				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
No Items						
Unit Totals:	0.00	0.00	0.00	0.00%	0.00	0.00
RD2075	Overall LMA Rating	Total LMA Miles	* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.			
Reclamation District No. 2075 McMullin	M *	7.52				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Vegetation	0.02		0.02	0.27%		
Trim / Thin Trees	0.04		0.04	0.53%		
Encroachments					0.52	
Crown Surface / Depressions / Rutting	0.01		0.01	0.13%		
Supplemental						
DWR Erosion Survey		0.01	0.04	0.53%		
LMA Totals:	0.07	0.01	0.11	1.46% *	0.52	0.00
RD2085	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 2085 Kasson	U	6.18				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Earthen Levee						
Vegetation	0.97		0.97	15.70%		
Trim / Thin Trees	0.09		0.09	1.46%		
Encroachments	0.34	0.01	0.38	6.15%	0.55	
Animal Control	0.04		0.04	0.65%		
Slope Stability	0.01		0.01	0.16%		
LMA Totals:	1.45	0.01	1.49	24.11%	0.55	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

Unit No. 01 San Joaquin River	Overall Unit Rating	Total Unit Miles				
RD2085	M	5.20				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.01		0.01	0.19%		
Trim / Thin Trees	0.09		0.09	1.73%		
Encroachments	0.34	0.01	0.38	7.31%	0.55	
Animal Control	0.04		0.04	0.77%		
Slope Stability	0.01		0.01	0.19%		
<i>Unit Totals:</i>	0.49	0.01	0.53	10.19%	0.55	0.00
Unit No. 02 San Joaquin River	Overall Unit Rating	Total Unit Miles				
RD2085	U	0.69				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.68		0.68	98.55%		
<i>Unit Totals:</i>	0.68	0.00	0.68	98.55%	0.00	0.00
Unit No. 03 San Joaquin River	Overall Unit Rating	Total Unit Miles				
RD2085	U	0.29				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.28		0.28	96.55%		
<i>Unit Totals:</i>	0.28	0.00	0.28	96.55%	0.00	0.00
RD2089	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 2089 Stark	U	2.90				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	1.21	0.33	2.53	87.24%		
Trim / Thin Trees	0.18	0.15	0.78	26.90%		
Encroachments	0.04		0.04	1.38%	0.41	0.05
Animal Control	0.05	0.01	0.09	3.10%		
Crown Surface / Depressions / Rutting	0.01		0.01	0.35%		
<i>Supplemental</i>						
DWR Erosion Survey		0.02	0.08	2.76%		
<i>LMA Totals:</i>	1.49	0.51	3.53	121.72%	0.41	0.05

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

Unit No. 01 Old River	Overall Unit Rating	Total Unit Miles				
RD2089	U	1.53				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.47	0.16	1.11	72.55%		
Trim / Thin Trees	0.13	0.15	0.73	47.71%		
Encroachments	0.01		0.01	0.65%	0.39	
<i>Supplemental</i>						
DWR Erosion Survey		0.01	0.04	2.61%		
<i>Unit Totals:</i>	0.61	0.32	1.89	123.53%	0.39	0.00

Unit No. 02 Salmon Slough	Overall Unit Rating	Total Unit Miles				
RD2089	U	1.37				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.74	0.17	1.42	103.65%		
Trim / Thin Trees	0.05		0.05	3.65%		
Encroachments	0.03		0.03	2.19%	0.02	0.05
Animal Control	0.05	0.01	0.09	6.57%		
Crown Surface / Depressions / Rutting	0.01		0.01	0.73%		
<i>Supplemental</i>						
DWR Erosion Survey		0.01	0.04	2.92%		
<i>Unit Totals:</i>	0.88	0.19	1.64	119.71%	0.02	0.05

RD2091 Reclamation District No. 2091 Chase	Overall LMA Rating	Total LMA Miles				
Not Inspected; 2009 Data	A	7.92				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>LMA Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

Unit No. 01 San Joaquin River	Overall Unit Rating	Total Unit Miles				
RD2091	Not Inspected; 2009 Data	A				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

Unit No. 02 San Joaquin River	Overall Unit Rating	Total Unit Miles				
RD2091	Not Inspected; 2009 Data	A				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

RD2092	Not Inspected; 2009 Data	Overall LMA Rating	Total LMA Miles			
Reclamation District No. 2092 Dos Rios		A	3.76			
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles
Earthen Levee						
Encroachments						0.83
Animal Control		0.04		0.04	1.06%	
Interior Drainage & Piping Systems						
Flap Gates		0.01		0.01	0.27%	
Supplemental						
DWR Erosion Survey		0.14		0.14	3.72%	
LMA Totals:		0.19	0.00	0.19	5.05%	0.83 0.00

RD2094		Overall LMA Rating	Total LMA Miles			
Reclamation District No. 2094 Wathal		A	3.28			
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles
No Items						
LMA Totals:		0.00	0.00	0.00	0.00%	0.00 0.00

Unit No. 01 San Joaquin River	Overall Unit Rating	Total Unit Miles				
RD2094	A	2.82				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles
No Items						
Unit Totals:		0.00	0.00	0.00	0.00%	0.00 0.00

Unit No. 02 San Joaquin River	Overall Unit Rating	Total Unit Miles				
RD2094	A	0.46				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles
No Items						
Unit Totals:		0.00	0.00	0.00	0.00%	0.00 0.00

RD2095	Overall LMA Rating	Total LMA Miles	* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.			
Reclamation District No. 2095 Paradise Cut	M *	4.83				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles
Earthen Levee						
Vegetation		0.05	0.01	0.09	1.86%	
Encroachments		0.01		0.01	0.21%	0.01
Supplemental						
DWR Erosion Survey		0.05	0.05	0.25	5.18%	
LMA Totals:		0.11	0.06	0.35	7.25% *	0.01 0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

Unit No. 01 Paradise Cut		Overall Unit Rating	Total Unit Miles	* Overall Unit Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall Unit Rating is M instead of A.			
RD2095		M *	1.45				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
Earthen Levee							
Encroachments		0.01		0.01	0.69%	0.01	
Supplemental							
DWR Erosion Survey		0.01	0.01	0.05	3.45%		
Unit Totals:		0.02	0.01	0.06	4.14% *	0.01	0.00

Unit No. 02 San Joaquin River		Overall Unit Rating	Total Unit Miles	* Overall Unit Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall Unit Rating is M instead of A.		
RD2095		M *	3.38			
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	0.05	0.01	0.09	2.66%		
Supplemental						
DWR Erosion Survey	0.04	0.04	0.20	5.92%		
Unit Totals:	0.09	0.05	0.29	8.58% *	0.00	0.00

RD2096	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 2096 Wetherbee Lake						
	M	0.17				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	0.01		0.01	5.88%		
Encroachments					0.13	
Animal Control	0.01		0.01	5.88%		
LMA Totals:	0.02	0.00	0.02	11.77%	0.13	0.00

RD2101	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 2101 Blewett						
	U	3.51				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Earthen Levee						
Vegetation	5.93		5.93	168.95%		
Trim / Thin Trees	0.26		0.26	7.41%		
Encroachments		0.25	1.00	28.49%	1.16	
Animal Control	0.04	0.01	0.08	2.28%		
Erosion / Bank Caving	0.02		0.02	0.57%		
Supplemental						
DWR Erosion Survey		0.10	0.40	11.40%		
LMA Totals:	6.25	0.36	7.69	219.09%	1.16	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

San Joaquin River Basin (cont.)

Unit No. 01 San Joaquin River	Overall Unit Rating	Total Unit Miles				
RD2101	U	3.20				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	5.63		5.63	175.94%		
Trim / Thin Trees	0.26		0.26	8.13%		
Encroachments		0.25	1.00	31.25%	1.16	
Animal Control	0.04	0.01	0.08	2.50%		
Erosion / Bank Caving	0.01		0.01	0.31%		
<i>Supplemental</i>						
DWR Erosion Survey		0.10	0.40	12.50%		
<i>Unit Totals:</i>	5.94	0.36	7.38	230.63%	1.16	0.00

Unit No. 02 San Joaquin River (Spur Levee)	Overall Unit Rating	Total Unit Miles				
RD2101	U	0.31				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.30		0.30	96.77%		
Erosion / Bank Caving	0.01		0.01	3.23%		
<i>Unit Totals:</i>	0.31	0.00	0.31	100.00%	0.00	0.00

RD2107 Not Inspected; 2009 Data	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 2107	A	4.21				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments	0.06		0.06	1.43%	0.01	
Slope Stability	0.01		0.01	0.24%		
<i>LMA Totals:</i>	0.07	0.00	0.07	1.66%	0.01	0.00

Unit No. 01 San Joaquin River	Overall Unit Rating	Total Unit Miles				
RD2107 Not Inspected; 2009 Data	A	2.37				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments	0.05		0.05	2.11%	0.01	
<i>Unit Totals:</i>	0.05	0.00	0.05	2.11%	0.01	0.00

Unit No. 02 Paradise Cut	Overall Unit Rating	Total Unit Miles				
RD2107 Not Inspected; 2009 Data	A	1.84				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments	0.01		0.01	0.54%		
Slope Stability	0.01		0.01	0.54%		
<i>Unit Totals:</i>	0.02	0.00	0.02	1.09%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

**Fall 2010 Levee Maintenance Deficiency Summary Report
Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey**

Miscellaneous Streams & Basins

MA0017	Overall LMA Rating	Total LMA Miles				
Sutter Maintenance Yard Maintenance Area 0017	U	3.90				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation		3.13	12.52	321.03%		
Trim / Thin Trees		3.12	12.48	320.00%		
<i>LMA Totals:</i>	0.00	6.25	25.00	641.03%	0.00	0.00

NA0009	Overall LMA Rating	Total LMA Miles				
Lake County Watershed Protection District	A	10.47				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.01		0.01	0.10%		
Trim / Thin Trees	0.02		0.02	0.19%		
Encroachments	0.01		0.01	0.10%	0.01	
<i>LMA Totals:</i>	0.04	0.00	0.04	0.38%	0.01	0.00

**Flood Control Project Maintenance
Levee Inspections**

**Fall 2010 Levee Maintenance Deficiency Summary Report
Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey**

Miscellaneous Streams & Basins (cont.)

Unit No. 01 Middle Creek	Overall Unit Rating	Total Unit Miles				
NA0009 Not Inspected; 2009 Data	A	3.42				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Trim / Thin Trees	0.01		0.01	0.29%		
<i>Unit Totals:</i>	0.01	0.00	0.01	0.29%	0.00	0.00
Unit No. 02 Middle Creek	Overall Unit Rating	Total Unit Miles				
NA0009 Not Inspected; 2009 Data	A	3.13				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.01		0.01	0.32%		
Encroachments					0.01	
<i>Unit Totals:</i>	0.01	0.00	0.01	0.32%	0.01	0.00
Unit No. 03 Scotts Creek	Overall Unit Rating	Total Unit Miles				
NA0009 Not Inspected; 2009 Data	A	1.35				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
Unit No. 04 Page, Alley and Clover Creek Diversion	Overall Unit Rating	Total Unit Miles				
NA0009 Not Inspected; 2009 Data	A	1.53				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Trim / Thin Trees	0.01		0.01	0.65%		
Encroachments	0.01		0.01	0.65%		
<i>Unit Totals:</i>	0.02	0.00	0.02	1.31%	0.00	0.00
Unit No. 05 Clover Creek and Clover Creek Diversion	Overall Unit Rating	Total Unit Miles				
NA0009 Not Inspected; 2009 Data	A	1.04				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
NA0015 Plumas County	Overall LMA Rating	Total LMA Miles				
Not Inspected; 2009 Data	A	3.22				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>LMA Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR & USACE Erosion Survey

Miscellaneous Streams & Basins (cont.)

Unit No. 01 North Fork Feather River		Overall Unit Rating	Total Unit Miles				
NA0015	Not Inspected; 2009 Data	A	1.89				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
No Items							
Unit Totals:		0.00	0.00	0.00	0.00%	0.00	0.00

Unit No. 02 North Fork Feather River		Overall Unit Rating	Total Unit Miles				
NA0015	Not Inspected; 2009 Data	A	1.33				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
No Items							
Unit Totals:		0.00	0.00	0.00	0.00%	0.00	0.00